Submit 3 copies

State of New Mexico

Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 copies to Appropriate District Office	Ene	Minerals and Natur	ral Re	sources Department		Rev	rised 1-1-89
DISTRICT I	OIL	CONSERVA	TIC	ON DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 8824		P.O. Box				30 025 27829	
DISTRICT II	ç	Santa Fe, New Me			5. Indicate Ty	pe of Lease	
P.O. Box Drawer DD, Artesia, NM	88210	Januar 0, 14017 1410	JA100	0,00,1200		STATE	FEE 🔯
DISTRICT III					6. State Oil /	Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM			1000				
(DO NOT USE THIS FORM FOR	PROPOSALS RESERVOIR. U	ND REPORTS ON TO DRILL OR TO DE SE "APPLICATION F R SUCH PROPOSAL	EPEN OR PE	OR PLUG BACK TO A	7. Lease Nam C H WEIR A	e or Unit Agreement Nam	6
1. Type of Well: OIL WELL	GAS WELL	OTHER			8. Well No.		
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.						14	
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240						or Wildcat MONUMENT TUBB	
4. Well Location		- '					
Unit LetterK	: 1980	Feet From The	SOUT	H Line and <u>1815</u>	Feet From T	he WEST Line	
Section 12	Townsh	ip20S	R	ange <u>37E</u> NM	/IPM	LEA COUN	ΓY
				B, RT,GR, etc.) 3575' KB			
11. Che	ck Appropria	te Box to Indicate	e Nat	ure of Notice, Repor	t, or Other [Data	
NOTICE OF INTER	OT NOITN		1	Sl	JBSEQUE	NT REPORT OF:	
		D ABANDON	П	REMEDIAL WORK		ALTERING CASING	
PERFORM REMEDIAL WORK	CHANGE		П	COMMENCE DRILLING OP	ERATION	PLUG AND ABANDONM	ENT 🗌
TEMPORARILY ABANDON] 0,,,,,,,			CASING TEST AND CEME			
PULL OR ALTER CASING] :RF/ACIDIZE/FRA	r	\boxtimes	OTHER:	_		
OTHER: PE	:RF/ACIDIZE/FRA			OTTEN.			
 Describe Proposed or Comple any proposed work) SEE RUL 	ted Operations E 1103.	(Clearly state all per	tinent	details, and give pertine	nt dates, inclւ	iding estimated date of	starting
1. MIRU. KILL WELL WITH 2% K	CL WATER. TO	OH W/ PROD. EQUIP	P. SET	TRBP AT 6700. PERF @	6360' - 6451' (夏 2 SPF.	
2. SET PACKER @ 6320. ACIDIZ	ZE TUBB PERF	S WITH 3500 GALS.,	15% N	NEFE. P=2600, 10 BPM'S			
3. FRAC TUBB PERFS W/ 61000	GALS 35# XL	GEL + 228000# 16/30	OTTA	AWA SAND. PUMP @ 35	BPM'S, P MA	X = 9200 PSI.	
4. TOH W/ TREATING PACKER,	CLEAN OUT TO	O RBP. EVALUATE	TUBB	PRODUCTION.			
5. TOH W/ RBP. TIH W/ DUAL P STAB INTO DUAL PACKER W	ACKER ON AB	O STRING., STAB IN 3. SWAB BOTH STR	NTO M	ODEL D PACKER @ 693 UNTIL FLOWING & RET	5' , SET DUAL URN WELL TO	PACKER @ 6300'. PRODUCTION.	

I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	ledge and belief.	Engineering Assistant	DATE	4/26/94
TYPE OR PRINT NAME Darrell J. Carrige			Telephone No.	397-0431
(This space for State Use) APPROVED BY	TITLE	ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	DATE AF	R 27 1994

RECEIVE

#PR 26 *994

OFFICE