

Submit 3 Copies
To Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

811 South First, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-025-27865

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement
Name:

McAllister

8. Well No.
4

9. Pool name or Wildcat
Nadine Paddock Blinbry, West

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Sapient Energy Corp

3. Address of Operator
8801 South Yale, Ste 150
Tulsa, OK 74137

4. Well Location
Unit letter _____ N _____ 660 _____ feet from the _____ South _____ line and _____ 660 _____ feet from the _____ West _____ line
Section 5, Township 20S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.
3585.5 DF

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON

TEMPORARILY ABANDON CHANGE PLANS

PULL OR ALTER CASING

OTHER: _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING

COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

OTHER: _____ Add Perfs _____

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

Add perfs to existing Blinbry zone.

12-14-00 MI and RU – pull rods and pump – pull tbg – perf Blinbry upper zone from: 5880-87', 5860-66', 5834-42', 5810-14' 5790-94', 5756-60' 66 shots, 2 spf, .44"

12-15-00 Isolate perfs from 5880-87' with packer and plug – acidize w/175 gallons 15% HCL acid

Isolate perfs from 5860-66' with packer and plug – acidize w/175 gallons 15% HCL acid

12-21-00 Isolate perfs from 5810-14', 5770-94', 5756-60 with packer and plug – acidize w/ 500 gallons 20% HCL acid and 1500 gallons 28% SXE acid.

12-22-00 Swab Test.

12-23-00 Put on production w/Blinbry perfs & Tubb perfs that were already producing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gerald Lucero TITLE Manager of Operations DATE March 7, 2001

Type of print name Gerald Lucero Telephone No. (918) 488-8988

(This space for State use)

APPROVED

BY Gerald Lucero TITLE Manager of Operations DATE March 7, 2001

Conditions of approval, if any: