Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

07505	DISTRICT I P.O. Box 1980, Hobbs, NM	88240 OII	CONSERVA 2040 Pach	ATIO	N DIVISION	WELL API NO. 30)-025-28277	·····
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS POPUL FOR PROPOSCALS TO DRILL OR TO DESPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSCALS) 1. Type of Well: ONE Note: Note:	DISTRICT II P.O. Drawer DD, Arlosia, NA	M 88210						[]
(DO NOT USE THIS FORM FOR PRIPOROSALS TO DEREN ON THE PLUG BACK TO A DIFFERENT RESERVOR. USE APPLICATION FOR PERMIT (FORM 0-101) FOR SUCH PROPOSALS) Type of Well.		NM 87410				6. State Oil & Gas I		FEE L
Type of Walt	(DO NOT USE THIS FOI	RM FOR PROPOSAL RENT RESERVOIR.	LS TO DRILL OR TO D USE "APPLICATION F	EEPEN (OR PER	OR PLUG BACK TO A			
Raptor Resources, Inc. Address of Operator 901 Rio Grande, Austin, Texas 78701 9. Food same or Wildcat Eunice SR Queen-South Well Leating Unit Letter E : 2570 Feet From The North Line and 70 Feet From The West Line Section 9 Township 228 Range 36E NMPM Lea County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) GTL-3385 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: T/A Status Test The Comment of Notice of Stating any proposed worth SEE RULe 1103. Test Date: 3-14-03 1. Load casing with 2% KCI water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years AuthOfficial Status for 5 years AuthOfficial Status for 5 years	OIL —	ans 🗀			r Injection Well	St	ate A A/C 2	
Well Location Unit Letter E : 2570 Feet From The North Line and 70 Feet From The West Line Section 9 Township 22S Range 36E NAMPM Lea Commy 10. Elevation (Show whether OF, RES, RT, GR, etc.) GL-3585 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CHANGE PLANS CHANGE DELLING OPNS. PLUG AND ABANDONMENT ULL OR ALTER CASING THER: TAS STATUS Test THE TYA STATUS Test STATUS Test TOTHER: TAS STATUS Test STATUS Te	Name of Operator	Raptor Reso	ources, Inc.					
Unit Letter E : 2570 Feet From The North Line and 70 Feet From The West Line Section 9 Township 22S Range 36E NMPM Lea County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) GL-3585 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	. Address of Operator	901 Rio Gra	ınde, Austin, Te	xas 78	701			
Section 9 Township 22S Range 36E NMPM Lea County 10. Elevation (Show whather DP, RKB, RT, GR, etc.) G1.3585 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ULL OR ALTER CASING OTHER: T/A Status Test 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103. Test Date: 3-14-03 1. Load casing with 2% KCl water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Date: 3-17-03	F	2570 Fe	et From The	North	Line and7	O Feet From 7	The West	Lin
10. Elevation (Show whither DF, RRS, RT, GR, etc.) GL-3585 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. LOCATION COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: T/A Status Test SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: T/A Status Test SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: T/A Status Test SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: T/A Status Test SUBSEQUENT REPORT OF PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: T/A Status Test SUBSEQUENT REPORT OF PLUG AND ABANDONMENT COMMENT TO THERE IS A STATE OF STATE O		0	ownship 22S	Ran	36E	7		County
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK			10. Elevation (Show	whether L	OF, RKB, RT, GR, etc.)			
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: T/A Status Test 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent date; including estimated date of starting any proposed work) SEE RULE 1103. Test Date: 3-14-03 1. Load casing with 2% KCl water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Describe Production Boove is true and complete to the best of my knowledge and belief. Production Foreman Date 3-17-03	= -		=	licate N				
CASING TEST AND CEMENT JOB OTHER: T/A Status Test OTHER: T/A Status Test DITHER: T/A Status Test DITHER: T/A Status Test DITHER: T/A Status Test DITHER: T/A Status Test Test Date: 3-14-03 1. Load casing with 2% KCl water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Abuitdoniment Expires DITHER: T/A Status Test Abuitdoniment Expires DITHER: T/A Status Test Thereby certify that the information above us true and complete to the best of my transvedge and belief. SIGNATURE TITLE ORIGINAL SIGNED BY CASING TEST AND CEMENT JOB OTHER: T/A Status Test Total date: including estimated date of starting any proposed and perfect to 500 psi for 30 minutes. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Abuitdoniment Expires ORIGINAL SIGNED BY CAST OF STATE DEPORTED ELECTRONIC MANUAL CAST OF THE PROPERTY AND THE MANUAL CAST OF THE PROPERTY AND THE MANUAL CAST OF THE PROPERTY AND THE PACKET MANUAL CAST OF THE PROPERTY AND THE PACKET MANUAL CAST OF THE PROPERTY AND THE PACKET MANUAL CAST OF THE PACKET MANUAL CAST O	ERFORM REMEDIAL WO	PRK P	LUG AND ABANDON		REMEDIAL WORK		LITERING CASING	
THER: OTHER: T/A Status Test	EMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING	GOPNS F	LUG AND ABAND	ONMENT [
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 1. Load casing with 2% KCl water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Description of Temporary 3/19/88	ULL OR ALTER CASING				CASING TEST AND C	EMENT JOB		
Test Date: 3-14-03 1. Load casing with 2% KCl water and corrosion inhibitor. (Packer @ 3714') 2. Pressure test casing from surface to 3714' to 500 psi for 30 minutes. (Record test on chart for OCD subsequent report.) 3. Request TA status for 5 years Description of Temporary 3/19/8	THER:				OTHER:T	/A Status Test		5
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Foreman DATE 3-17-03 THE PRODUCTION FOREMAN (505) TELEPHONE NO. 394-2574 ORIGINAL SIGNED BY CARY W. THENK DATE ORIGINAL SIGNED BY CARY W. THENK OCHELD REPRESENTATIVE INSTACE MARKAGES	Tes 1. I	t Date: 3-14-03 Load casing with the case of the case	sing from surface	to 371	4' to 500 psi for 3		')	
THE OR PRINT NAME Incl Sisk ORIGINAL SIGNED BY APPROVED BY APPROVED BY OCCUPANTIAL SIGNED BY CARY W. THIRNK CA	3. 1	Request TA stat	tus for 5 years.					
SIGNATURE Production Foreman 3-17-03 TYPE OR FRINT NAME JOEI SISK (505) TELEPHONE NO. 394-2574 (This space for State Use) ORIGINAL SIGNED BY CARY W. HAINK OCCEPTED REPRESENTATIVE MASTAGES AND AND ACCES			Sparoval (Bandonment Ex	of Tem pires	sporary 3/1	9/08	10	
TITLE DATE TYPE OR PRINT NAME JOEI SISK (505) TELEPHONE NO. 394-2574 (This space for State Use) ORIGINAL SIGNED BY CARY W. THIBNK OCCUPANTIAL STATE MAANAGES	I hereby certify that the inform	ation above is true and con	uplete to the best of my know	wiedge and			2 17 0	2
(This space for State Use) ORIGINAL SIGNED BY ORIGINAL SIGNED BY	SIONATURE	of Sisk		тіг	roduction rote		DATE	
ORIGINAL SIGNED BY CARY W. THUNK CC EIEU REPRESENTATIVE ILICATE MANAGES	TYPE OR PRINT NAME	Jne	Sisk			(505)	TELEPHONE NO.	394-2574
OC FIELD REPRESENTATIVE ILICATE MANAGES	(This space for State Use)		ORIC	GINAL S	SIGNED BY		MAR 1 9	2003
CONDITIONS OF APPROVAL, IF ANY:	APTROVED BY		<u> </u>	YW. 😘	CORCELETATIVE II O	AT THE WAY THE SECOND	DATE	
	CONDITIONS OF APPROVAL, IP	ANY:		Davie (p)	CONTRIBIATIVE II/S	INTERMACE		

