

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-28699
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1536
7. Lease Name or Unit Agreement Name STATE E
8. Well No. 13
9. Pool name or Wildcat EUNICE 7 RS-ON SO.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator CONOCO INC.
3. Address of Operator 10 Desta Drive, Ste 100-West, Midland, Texas 1-915-686-5580
4. Well Location Unit Letter <u>N</u> : <u>990'</u> Feet From The <u>South</u> Line and <u>2310'</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>22S</u> Range <u>36-E</u> NMMPM Lea County
10. Elevation (Show whether DP, RK3, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/30/00- Rig up equip and Gih w/2 3/8 work string, and tag at RBP at 3720' try to load casing 5 1/2" 15.5 lb. Pump 100 bbl brine and shut down, well on a vaccum, could not load casing called billy prichard state inspector and got ok to set CIBP at 3620': Set 5 1/2" CIBP at 3620' load casing w/brine gel and test from 3620' to surface 500 psi held and circulated casing w/brine gel and spot 25 sks class C cmt bottom 3622' tag top of cmt at 3370' on july 1,00, laid down tubing to 1700' spot a 25 sks plug bottom 1700' top at 1450' lay down tubing to 1150' spot a 25 sks plug bottom 1150' pull out of hole to 500' shut down, July 5, 00- tag top of plug at 895', laid down tubing to 98' and spot 10 sks surface plug bottom 98' top of cmt at surface, cut off well head and install dry hole marker rig down cut off anchors and clean up location and move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronald L. Walker TITLE CMT Sup. DATE 7-5-00

TYPE OR PRINT NAME Ronald L. Walker, Pool Co. TELEPHONE NO. 505/392-6591

(This space for State Use)

APPROVED BY [Signature] TITLE Field Sup DATE 4-3-01

CONDITIONS OF APPROVAL IF ANY:

cc: BLM(6), OGD(1), SHEAR, POWCA, COST ASST, FIELD, FILE ROOM

