

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28849
5. Indicate Type of Lease	STATE FEE ☒
6. State Oil / Gas Lease No.	879910
7. Lease Name or Unit Agreement Name	WEIR, C. H. -A-
8. Well No.	15
9. Pool Name or Wildcat	WEIR BLINEBRY EAST/SKAGGS DRNKRD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3575' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>988</u> Feet From The <u>EAST</u> Line Section <u>12</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3575' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	DHC ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-13-00: MIRU. PUMP STUCK. RU FOAM UNIT.
7-14-00: INSTL BOP. WRK STUCK TBG. PUMP 100 BBLs 2% DN BACKSIDE. WORK TBG LOOSE. SWAB TBG TO 4700'.
7-17-00: TIH W/CONE BUSTER MILL, DC'S ON WS. STOP BIT @ 5212'.
7-18-00: BREAK CIRC W/FOAM UNIT @ 5212'. TIH W/WS. TAG @ 5943'. PLUGGED TBG. LOWER TOOLS & TAG @ 5943'. C/O SCALE 5943-6093. PULL MILL TO 5441'.
7-19-00: LOWER TOOLS & TAG @ 6093'. MILL OUT TIGHT SPOT 6093-95. C/O SCALE 6095-6140. LOWER TOOLS & TAG @ 6495'. C/O TO CIBP @ 6593'. DRILL ON JUNK & CIBP. PULL MILL TO 5187'.
7-20-00: TIH W/BIT & DC'S ON TBG. TAG CIBP @ 6594'. DRILL 1 HR. PULL UP TO 5823'. LOWER TOOLS & TAG @ 6594'. DRILL ON CIBP & TURNED LOOSE. PUSH TO 6617'.
7-21-00: LOWER TOOLS & TAG @ 6877'. PULL TO 5472 W/FOAM UNIT. LOWER TOOLS & DRILL ON CIBP @ 6877'. PUSH TO 6893'. TIH W/SONIC HAMMER TOOL TO 2872'.
7-24-00: KILL W/40 BBLs 2% KCL WTR. TIH W/SONIC HAMMER & INSTL STRIPPER HEAD. ACID WASH BLINEBRY & DRINKARS PERFS 5726-5943'. 6634-6873. W/3000 GALS 15% NEFE HCL & 240 BBLs 2% KCL WTR. RU SWAB. FL @ 4300'. END FL @ 5000'. RD SWAB.
7-25-00: RAN PROD STRING: MUD ANCHOR, PURGE VALVE, SN, TBG, TAC. MA @ 6869'. SN @ 6836'. TAC @ 5663'. NDBOP. SET TAC. FLANGE UP WH. RAN PUMP & RDS.
7-26-00: CHANGE OUT ALL RD BOXED.
7-27-00: LOAD/PSI TBG TO 500-OK. RIG DOWN.
8-15-00: ON 24 HR OPT. PUMPED 48 BO, 153 BW, & 92 MCF. PERFS: 5726-6873 BLINEBRY/DRINKARD
SPLITS: BLINEBRY OIL - 11, WTR - 38, MCF - 63
DRINKARD OIL - 37, WTR - 115, MCF - 29

ORDER #R-11363

FINAL REPORT

I DHC Order No. 0005

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 8/24/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

ORIGINAL SIGNED BY CHIEF OF DIVISION
DISTRICT I SUPERVISOR

NOV 28 2000

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

DATE