AND MINERALS DEPARTM				•
or tories agetives	OIL C VSERV			
DISTRIBUTION	P. O. BOX 2088			Form C-103
ITAPE	SANTA FE, NEW MEXICO 87501			Revised 10-1-
.€			5a. Indicate T	/pe of Lease
1.0.1.			State	Foo X
PERATOR	-		5, State Oil &	Gas Lease No.
1	ے 30	) <b>-</b> 02 <b>5-</b> 28849		
SHIND	RY NOTICES AND REPORTS ON	IWELLS		THITTI
(DO NOT USE THIS FORM FOR P.	AOPOSALS TO DRILL OR TO GEEPEN OR PLUG ATION FOR PERMIT - " (FORM C-101) FOR SU	BACK TO A DIFFERENT RESERVOIR.	. (((((((	
			7. Unit Agreem	ient Name
ii X	OTHER-			
ie of Operator			8. Farm or Lea	
TEXACO Inc.			C. H. Wei	.r "A"
ireas oi Operator			9. Well No.	
P. O. Box 728, Hobbs, New Mexico 88240			15	
cation of Weil			LD. Field and I	Pool or WHdcm rinkard
INIT LETTER H	1980 FEET FROM THE North	988	Skaggs DI	Inkaru
THEFT CETTER	PEET PROM THE	LINE AND	TITITI SON IN	
East	12 TOWNSHIP 20-5	37 <b>-</b> E	HMPM.	
THE LINE, SECT	TOWASHIP	RANGE		
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	THITTE
		3559 <b>' (</b> GR)	Lea	
Describe Proposed or Completed (	PLUG BACK T 13 3/8" OD 54.5# 8 5/8" OD 32#	CASING TEST AND CEMENT JOB Perforate, other Perforate, ot	Treat and Compliancial date of 1453 1000 1	L
70, 20, 58, 2. SET W/ 3 3. RESI W/ 0	FORATE 5 1/2" CSG W/7 76, 78, 82, 85, 90, 23, 28, 32, 38, 45, 46, 62, 69, & 6873'.  RBP @ 6900' AND PKR 8000 GALS 15% NEFE ACT RBP @ 6770' AND PKR 6000 GALS 15% NEFE A RBP.  2 3/8" TUBING W/PKR 7 TALL PRODUCTION EQUIPMENT	93, 97, 99, 670 17, 6810, 17, 26, @ 6770'. ACIDIS ID AND 35 BALL SE R @ 6560'. ACIDI CID AND 75 BALL	1, 06, 09, 13 32, 38, 43, 43, 42 ZE PERFS 6810- ZE PERFS 6634 SEALERS. PUL	-6873' -6747' L PKR
	on above is true and complete to the best		T 10	-24-84

NOV - 1 1984

ORIGINAL SIGNED BY IERRY SEATON BUTSAIT I SUPERVISOR