

SEMU Burger B #121: 30-025-29089

10/19/99 The repairs made to this well were simply removing the old, leaking valve and replacing with a new one. A new chart was then run.

Future plans are to recomplete this well in early 2000, pending funding.