

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		7. Unit Agreement Name
Name of Operator Fred G. Yates, Inc.		8. Form of Lease Name Amoco "12"
Address of Operator Sunwest Centre, Suite 1010, Roswell, NM 88201		9. Well No. 1
Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM West LINE, SECTION 12 TOWNSHIP 20S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, CR, etc.) 3566' G.L.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Due to the fact that the well is incapable of producing in commercial quantities, it was plugged and abandoned as follows:

8/27/85: Pulled rods, pump and tubing and prepared to set plug #1.

8/28/85: Set Plug #1 (2 sacks) from 4200'-4300'. Cut & pulled 74 joints 4½" casing.

8/29/85: Set Plug #2 (25 sacks) 50' into 4½" stub and 50' above @ 3165'-3065'. Jack Griffin of OCD as witness. Placed Plug #3 (35 sacks) 1634'-1534'.

8/30/85: Placed regulation 4" X 10' marker in 10 sacks cement at surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHECKED <u>John H. Griffin</u>	TITLE <u>Engineer</u>	DATE <u>1/13/86</u>
APPROVED BY <u>R. A. Adair</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 24 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 14 1986

O.C.D.
HOBBS OFFICE