## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

## OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION	P. O. BOX 2088		Revised 10-1-78	
SANTAFE	SANTA FE, NEW MEXICO 87501			
PILE			State For X	
U.S.O.S.			5. State Oil & Gas Lease No.	
OPERATOR			5. State On a Good Barrer	
			VIIIIIIIIIIIII	
SUNDRY	NOTICES AND REPORTS ON	WELLS		
OP NOT USE THIS FORM FOR PROPO USE "LAPPLICATION	FOR PERMIT -" IFORM C-1013 FOR SUC	H PROPOSALS.)	7. Unit Agreement Name	
ALL CY CAR				
werr XT were L	OTHER-		8. Farm of Lease Liame	
. Name of Operator			Amoco "12"	
Fred G. Yates, Inc.			9. Well No.	
3. Address of Operator	010 Poswell NM 88201		1	
Sunwest Centre, Suite	919, Roswell, NM 88201		10. Field and Pool, or Wildcat	
4. Location of Well	60 North	LINE AND 660 FEET FROM	Undesignated	
UNIT LETTER	FEET FROM THE	LINE AND		
Noc+	12 20\$	RANGE 38E NMPM	AHHHHHHHHH	
THE WEST LINE, SECTION			111111111111111111111111111111111111111	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
	3566' (	G.L.	Lea	
16. Chack A	ppropriate Box To Indicate	Nature of Notice, Report or Ot	her Data	
NOTICE OF INT		SUBSEQUEN	T REPORT OF:	
NOTICE OF III				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ASANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	П	
POLE ON ALTER CHOING		OTHER		
DTHER				
	(Classly state all pertinent de	tails, and give pertinent dates, includin	ig estimated date of starting any proposed	
17. Describe Proposed or Completed Open work) SEE RULE 1103.	rations (Clearly state are personnel			
2/20/85: Re-acidized wi				
swabbing.	swabbing.			
2/21 - 2/23/85: Swabbin	g.			
2/24/85: Shut down for Sunday. 2/25/85: Rig up Schlumberger & set cast iron bridge plug at 7054'; Perforate 7037-39' with 4 SPF 2/25/85: Rig up Schlumberger & set cast iron bridge plug at 7054'; Perforate 7037-39' with 4 SPF				
2/25/85: Rig up Schlumberger & set cast from Bridge plug at 7054; respectively and re-perforate 7010-26' with 1 SPF. Halliburton fracked down casing with 50,000 gallor				
and re-perforate 7010-26' with 1 SPF. Hallibulton fracted down outside the versage 1400 and 43,500# Ottawa sand.				
versagel 1400	and 43,500% Octawa same	flowing back @ 9:50 a.m.	•	
2/26/85: Running temperature survey; starting flowing back @ 9:50 a.m.				
2/27/85: Rig up & begin				
2/28 - 3/4/85: Swabbing		wered tubing to PBTD 7054	, <b>1</b> <b>4</b> •	
3/5/85: Swabbed 9 hours	by-passed packer, io	anchor in tension at 6984	4'; PSN @ 6980'. Ran rods	
3/6/85: Ran 214 joints	2 3/8" tubing, landed a	allehor in tempton at the	•	
<del>-</del>	& hung on clamp.	<b>a</b>		
3/7/85: Preparing to se	et pumping unit & engine	<b>= •</b>		
	•			
18. I hereby certify that the information	above is true and complete to the be	at of my knowledge and belief.		
	M- 1/2 -	•	3/7/85	
1 hothmall	The Theservice	Engineer	DATE 3///03	
alento the first the			11 n	
ORIGINAL SIGNED	D BY JERRY SEXTON	·	MAR 1 1 1985	
DISTRICT I	SUPERVISOR		DATE	