STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

. ** *** **	****	\top		_
DISTRIBUT	G=	╁	7	_
SAMTA FE		+	÷	
FILE		÷	- 	÷
U.1.0.4.		÷	÷	-
LANG OFFICE		 -	÷	
TRANSPORTER	air	i	 -	ᅱ
	GAS	ī	\neg	ᅥ
POTATO		1	\top	ᅥ
PROMATION OFF	ĸz	ī	+	⊣

OIL CONSERVATION DIVISION

P. O. BOX 2088 SANTA FE, NEW MEXICO 87501 Form C-104
Revised 10-01-78
Format 06-01-83
Page 1

REQUEST FOR ALLOWABLE AND

ALITI IDDIT I TION	AND
I. AUTHORIZATION TO TRA	UNSPORT OIL AND NATURAL GAS
Chevron U. S. A. Inc.	
P. O. 670 Hobbs Name :	
P. O. 670, Hobbs, New Mexico 88240 Reason(s) for felling (Check proper box)	
New Well Change in Transporter al:	Other (Please explain)
Recompletion X Oil	
Change in Ownership	Dry Gas Condensate
If change of ownership give name	Contensate
and address of previous owner	•
II DESCRIPTION OF WITH	
II. DESCRIPTION OF WELL AND LEASE	
Eunice Monument South Unit 49 Eunice Monu	
Location 10082030	State, Federal or Fee State
Unit Letter H: ## Feet From The Morth	1,0760
2.1	ine and the Free From The Color
Line of Section 3/ Township 205 Range	37E . NMPM. Lea
III. DESIGNATION OF TRANSPORTED OF THE	Title Annual Co.
Name of Authorized Transporter of OIL AND NATURA	AL GAS
ARCO, Shell, & Texas New Mexico Pineline	Address (Give address to which approved copy of this form is to be sent)
Hame of Authorized Transporter of Castingheda Gas X or Dry Gaz	
Phillips 66 Natl Gas CONFGLE CUPPO No. 1992	Address (Give address to watch approved copy of this form is to be sent)
If well produces oil or liquids, Unit See Twp. Rgs.	is gas actually connected? . When
1/1 7 (21) . 265	14.5
If this production is commingled with that from any other lease or pool,	give commingling order numbers
NOTE: Complete Parts IV and V on reverse side if necessary.	
VI. CERTIFICATE OF COMPLIANCE	11
	OIL CONSERVATION DIVISION
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given is true and complete to the best of my knowledge and belief.	APPROVEDJAN 1 3 1987
ny knowledge and belief.	. 19
	BYORIGINAL SIGNED BY JERRY SEXTON
<u></u>	TITLE SISTRICT SUPERVISOR
- Chara Coll o	This form is to be filled.
New Mexico Area Supt.	This form is to be filed in compliance with RULE 1104. If this is a request for allowable for a newly drilled or despended well, this form must be accompanied by a newly drilled or despended.
New Mexico Area Mupt.	well, this form must be accompanied by a tabulation of the deviation
(Title)	All sections of this for much and the
1-14-81	All sections of this form must be filled out completely for allowable on new and recompleted wells.
(Date)	Fill out only Sections I. II. III. and VI for changes of owner, well name or number, or transporter, or other such change of condition.
	Separate Forms Cains much be the standard change of conditions
"	completed wells.

	Oil Well ' Gas We	11 11 11				
Designate Type of Complet		New Well Workover	Deepen	Plug Becz -	Same Resty, Ditt. Res	
Date Spudded	Date Compi. Ready to Prod.	Total Deptn		P.S.T.D.	· · · · · · · · · · · · · · · · · · ·	
Elevations (DF, RK3, RT, GR, etc.,	Name of Producing Formation	Top OII/Gos Pay	Top OII/Gos Pay		Tubing Cepth 1.1.1	
eriorations		Depth Casing Shae			g Shqe	
	TUBING, CASING.	AND CEMENTING RECORD				
HOLE SIZE	CASING & TUBING SIZE	OEPTH SET		- SA	CKS CEMENT	
<u></u>		•				
	<u> </u>					
		!				
'. TEST DATA AND REQUEST	T FOR ALLOWABLE (Test must	be after recovery of total valume (a depth or be for full 24 hours)	of load oil a	nd must be so	ual to or exceed top allo	
Date First New Cil Bun To Tones			umo, car lift	. esc. /	· · · · · · · · · · · · · · · · · · ·	
Date First New Cil Run To Tanks	Date of Test	Producing Method (Flow, p	ump, gas lift	, e.c.)		
			ump, zas lift	Chore Size		
Date First New Cit Run To Tanks Length of Teet Actual Prod. During Test	Date of Test	Producing Method (Flow, p	ump, gas lift			
Length of Teet Actual Prod. During Test	Date of Test Tubing Pressure	Producing Method (Flow, p	ump, gas lift	Chore Size		
Langth of Test Actual Prod. During Test CAS WELL	Date of Test Tubing Pressure	Producing Method (Flow, p	wmp, gas lift	Chore Size	ondensqte	
Length of Teet	Date of Test Tubing Pressure OH-Sbis.	Producing Method (Flow, p Claim Pressure Water-Bbis.	ump, gas lift	Chore Size	and en eque	