STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO, BY COPIES RECEIVED	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

P. O. BOX 2088

ATMAR	FE.	NEW	MEXICO	87501

Form C-103 . Revised 10-1-78

BANTA FE	SANTA	FE, NEW	MEXICO 87501			
FILE				Sa. Indicate Tys	oe of Lease	
U.S.G.S.	_			State X	Fee	
LAND OFFICE	<u>.</u>			5. State Oil & C	as Lease No.	
OPERATOR	٠ .			E-	267	
	THE NOTICES AND DEE	ODTS ON V	WELL C	MITTE	TITITITI.	
SUND	RY NOTICES AND REP	OK IS UN Y	YELLS CK TO A DIFFERENT RESERVOIR. PROPOSALS.)		1//////////////////////////////////////	
USE "APPLICA	TION FOR PERMIT -** (FORM C	-101) FOR SUCH	PROPOSALS.	7, Unit Agreeme	ent Name	
. oir &∆						
MELL XX	OTHER-			8. Form or Leas	se Name	
2. Name of Operator					North Lake	
Magnatex Corpo	ration			9. Well No.	ake	
3. Address of Operator						
One Marienfeld	Place, Suite 405,	Midland	, TX 79701	<u>]</u>	and or Wildow	
4. Location of Well	•			10. Field and Pool, or Wildcat		
K	1980	South	LINE AND 1980 FEET FR	Jalmat (Jalmat (Yates)	
UNIT LETTER						
TT t-	2	22S	RANGE 35E NMF	([[[]]])		
THE WEST LINE, SEC	TION TOWNS			VIIIIII	71.7777777	
mmmmmm	15. Elevation (S	Show whether I)F, RT, GR, etc.)	12. County		
	3574.60			Lea		
	777777		Charles Depose of (Debas Dasa		
		Indicate N	ature of Notice, Report or (UT DEDORT OF	 .	
NOTICE OF	INTENTION TO:	ļ	SUBSEQUE	NT REPORT OF	**	
			<u></u>			
PERFORM REMEDIAL WORK	PLUG AND	ABANDON	REMEDIAL WORK		ERING CASING XX	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLU	S AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PL	AH5	CASING TEST AND CEMENT JOB			
7002 011 127 121 121 121 121 121 121 121 121 1		į	OTHER			
OTHER						
				·	of starting any proposes	
17. Describe Proposed or Completed	Operations (Clearly state all	pertinent deta	ils, and give pertinent dates, includ	ing estimated date c	n starting any proposed	
work) SEE RULE 1103.						
RU PU and bled pr	ressure off well.	Pulled p	ump and rods, then pul	led tbg. RI	.H open	
ended to 3930'.	Circulated hole w	/9.2# mud	. Set plug #1, 20 sxs	from 384/'	up.	
Waited 3 hrs. and	l tagged top at 370	02 '. Set	remaining plugs as fo	11ows:		
				•		
	#2	20 sxs	1805-1905'			
	#3	20 sxs	350-450 '			
	#4	4 sxs	at surface			
	. " ·					
Welded can on tor	and set 4' ident	ifving ma	rker. Well P&A'ed 7/2	23/86.		
werded cap on top	and see					
Coaine loft in h	ole: 400' 8 5/8"					
Casing left in ho	4000' 4 1/2"					
	4000 4 1/2			÷		
•						
				¥*		
18. I hereby certify that the informat	ion above is true and comple	te to the best of	of my knowledge and belief.			
					1-104	
Rannie Cam	10h Ad)	Pı	roduction Secretary	8	/5/86	
SIGNED IVANIUS COTT						
0 1			a a caratane	D	1V 1 0 1007	
(i) 10 V	1/1/2.		& GAS INSPECTO	DATE MA	4Y 1 2 1987	
APPROVED BY VE CE THE	a ve	TITLE				