State of New Mexico Form C-103 Submit 3 copies to Appropriate District Office Energy inerals and Natural Resources Department Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30 025 30317 DISTRICT II Santa Fe, New Mexico 87504-2088 5 Indicate Type of Lease P.O. Box Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil / Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 880140 SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT WEIR, C. H. -B-(FORM C-101) FOR SUCH PROPOSALS.) OIL GAS 1. Type of Well: \boxtimes WELL WELL **OTHER** 8 Well No 2. Name of Operator 10 TEXACO EXPLORATION & PRODUCTION INC. 9. Pool Name or Wildcat 3. Address of Operator 205 E. Bender, HOBBS, NM 88240 SKAGGS ABO 4. Well Location Feet From The SOUTH Line and 410 Feet From The EAST 1790 Line Unit Letter _ Range 37E Section 11 NMPM _ LEA COUNTY Township_ 10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3583 KB 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK П REMEDIAL WORK ALTERING CASING PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPERATION TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING Recomplete to Skaggs Abo OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 8-28-96: MIRU PRIDE. TOH W/ RODS & PUMP INSTALL BOP & POH W/ TBG. SDFN 8-29-96: TIH W/TOOLS & TAG FILL 6804, UNABLE TO GET CIRC DRY DRILL TO 6820, PULL UP TO 6599'. 8-30-96: RU FOAM UNIT. LOWER TOOLS TO 6820' CLEAN OUT SCALE TO 7071' CIRC. SDFN. 8-31-96; CLEAN OUT FROM 7071' TO 7150' (PBTD). DRY DRILL 2' CORE. POH. NO RECOVERY. 9-3-96: RAN FISHING TOOLS. POH. RECOVERED 1 EXPENDED PERFORATING GUN. SI. 9-4-96: TIH W/ CMT RET. TESTED TO 5000#. SET RET. @ 6555'. LOAD & TEST BACKSIDE TO 500# OK. RU DOWELL. PUMP 100 SKS CLASS H 15.6#/GAL TAILED IN W/ 50 SKS CLASS H NEAT STAGE IN LAST 11 BBLS. MAX PRESS=760#, MIN PRESS=VACUUM, AIR=2BPM.SQUEEZED DRINKARD PERFS. 6674'-6879'. 9-5-96: TOH W/TBG.TIH W/BIT, TAG CMT RET, 6555', DRILL UP CEMENT RETAINER TO 6638' CIRC, CLEAN, 9-6-96: DRILL CMT FROM 6638'-6895', TEST CSG TO 300#, LEAK OFF TO 0 IN 5MINS. LOWER TOOLS & PUSH CMT RET. TO 7150', CIRC, CLEAN,

9-6-96: DRILL CMT FROM 6638'-6895'. TEST CSG TO 300#,LEAK OFF TO 0 IN 5MINS. LOWER TOOLS & PUSH CMT RET. TO 7150'. CIRC. CLEAN TOH W/ TBG. & TOOLS. SDFN

9-7-96:TIH W/CMT RET & SET RET @ 6555'.RE-SQUEEZE DRINKARD PERFS 6874'-6879', STAGE IN CEMENT. DISPLACE TO BOTTOM OF RETAINER .STING OUT OF RETAINER & POH W/ TBG. MAX PRESS=1500#, MIN PRESS=830#, 14.8#. 9-8-96: WOC 20 HRS. 9-9-96: WOC 44 HRS. 9-9-96: TIH W/ BIT.TAGGED CMT RET. @6556. DRILL UP CMT RET, 6558'-6720' FELL THROUGH. LOWER TOOLS TO 6890' PRESSURE CSG TO 300# FOR 30 MINS-NO LEAK OFF. CIRC CLEAN SDFN.

9-10-96: PICKLE TBG. W/ 500 GALS 15% NE FE HCL & REVERSE OUT. PULL UP TO 7138' & SPOT 100 GALS 15% NE FE HCL. RD DOWELL. TOH W/ TBG & TOOLS. RU HALIB. & PERF. SKAGGS ABO FORM. W/2 JSPF AS FOLLOWS; 7066'-7132'. 18' NET, 66' GROSS, 36-.45" HOLES.TOH RD HALIB.TIH W/ PKR, SET PKR @ 6974'. SDFN

9-11-96: REMOVE BOP & INSTALL 3000# TREE. LOAD & TEST BACKSIDE TO 300#. ACIDIZE SKAGGS ABO PERFS.7066'-7132' W/ 3500 GALS 15% NE FE HCL AND 54 7/8 BALLS. MAX PRESS=5000#,MIN PRESS=2000#,AIR=3.5BPM, ISIP=VACUUM.SI WELL SDFN.

9-12-96: RIG UP SWAB, SWAB 3-1/2 HRS REC 30 BBLS LOAD. WELL KICKED OFF FLOWINGTO PIT. 50# FTP. START LAYING DOWN RODS. SDEN

9-13-96: HOOKUP TO FLOWLINE TO BTTY.ON PRODUCTION AT 9 AM. FLOWING ON 10/64" CHOKE, LAYDOWN RODS, RD.

9-14-96 THRU 10-8-96: TESTING.

10-9-96: OPT 1-BO, 0-BW, 380-MCF.

ORDER NO. R-10678, UNORTHODOX LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineering Assistant			DATE 400400
SIGNATURE COUNTY	IIILE		DATE 12/11/96
TYPE OR PRINT NAME Paula S. Ives			Telephone Nc. 397-0432
(This space for State Use) ORAGINES CHARGES AND A REPORT TRANSPORT			JAN 3 0 1297
APPROVED BY	isinica too alamana Title_		DATE
CONDITIONS OF APPROVAL, I	ANY:		

2A Skaggs Drinkard

JC