State of New Mexico Ene. Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

WELL API NO.	
30-025-30459	
5. Indicate Type of Lease	. === [

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 1980, Hobbs, NM 88240	WELL API NO.	
P.U. Box 2088	30-025-30459	
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE XX FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG 07267	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAY DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1011) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name 00 2306	
1. Type of Well:	Chiso -D- 8711 JV-P	
OIL CAS OTHER		
2. Name of Operator	8. Well No.	
BTA Oil Producers		
3. Address of Operator	9. Pool name or Wildows.	
104 S. Pecos, Midland, TX 79701	Wildcat (Strawn)	
4. Well Location		
Unit Letter K : 1980 Feet From The South Line and 2310 Feet From The West Line		
Section 23 Township 22S Range 34	E NMPM Lea County	
V///////	· · · · · · · · · · · · · · · · · · ·	
XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	ORK ALTERING CASING	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT XX		
PULL OR ALTER CASING CASING TEST AND CEMENT JOB		
		
OTHER: OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed		
work) SEE RULE 1103. Approved as to plugging of the Well Bore.		
Liability under bond is retained until		
12-07-96 - MI & RU Pulling Unit, ND flowline surface restoration is completed.		
•		
12-10-96 -ND WH, NU- BOP, Load csg. rel pkr., POH w/ tbg & pkr.		
12-11-06 - DI DIM Wireling: Set 5" CIPD 6 11 0501 cm m/ 2 mm to 11 0001		
12-11-96 - RU P&M Wireline; Set 5" CIBP @ 11,850' cap w/ 3 sx to 11,809' Set 7-5/8" CIBP @ 10,750' cap w/7 sx to 10,713'		
Set 7-576 CIBP @ 10,750	cap w// sx to 10,/13	
12-13-96 - Circ hole w/9.3# salt gel mud. Spot 40 sx	amt nlug 0 0 7501 05201.	
Spot 40 sx cmt plug @ 5914' - 5680'; Spot	40 sx cmt plug @ 5006' - 4780'	
12-14-96 - Spot 40 sx cmt plug @ 3512' - 3280'; Spot 40 sx cmt plug @ 1250' - 1030';		
Spot 10 sx cmt plug @30' to Surface P&A 12-14-96		
12-16-96 Cut Off well head & installed P&A Marker		
I hereby certify that the information above/is type and complete to the just of/my knowledge and belief.		
SKINATURE Administrator DATE TIME REGULATORY Administrator DATE		
SIGNATURE THE REGULATION	y Administrator DATE 12-19-96	
SKINATURE TYPE OR PRINT NAME	y Administrator DATE 12-19-96 TELEPHONE NO.	

Approved as to plugging of the Well Bore.

APPROVED BY GARY WINK

CONDITIONS OF APPROPRISE DAYE PRESENTATIVE II/STAFF MANAGER Liability under bond is retained until DATE.

SURface restoration is completed

FC 2 :