

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30516
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1536
7. Lease Name or Unit Agreement Name State E
8. Well No. #14
9. Pool name or Wildcat Langley Strawn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3536' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Conoco Inc.
3. Address of Operator P.O. Box 460 - Hobbs, NM 88240	4. Well Location Unit Letter P : 330 Feet From The South Line and 660 Feet From The East Line Section 17 Township 22S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3536' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Complete Upper Strawn <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-2-89 MIRU, POOH w/rods & pump, pull packer to 9300', spot 3 bbls 15% HCL-NE-FE acid 9300' - 9170'. RIH w/4" HSC 180° phased 2 JSPF, 40 EHD, perf upper Strawn 9200' - 9220' & 9270' - 9296' (2 runs 92 shots). Circ wellbore clean w/485 bbls 2% KCL w/clay-stay. Acidize Strawn intervals 9200' - 9220' & 9270' - 9296' w/120 bbls 15% HCL-NE-FE acid. Drop 7 ballsealers every 5 bbls.

5-16-89 RIH w/pump & rods.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE June 25, 1989

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Eddie W. Seay
Oil & Gas Inspector

JUL 06 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: