Form 150- November 1 Shormerly 9	985.	BUREA		TATES THE INTERI	OR verse side)	TRIPI SATE:	Expires Ada 5. LEASE DESIGNATI NM-43564	ON AND BERIAL N	
(Do :				to deepen or plug b RMIT—" for such pr		IVEU reservoir.	6 IF INDIAN, ALLOT	THE OR TRIBE NAME	
	GAS WELL	OTHER			JUL 9 10	59 AN '91	7. UNIT AGREEMENT	NAME	
2. NAME OF OPERATOR					CARL OE 8. FARM OR LEASE NAME			NAME	
Oryx Energy Company					AREA		Ojo Chiso Fed		
P. O. Box 1861, Midland, TX 79702							1		
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with See also space 17 below ) At surface</li> </ol>					State requirements	•	Ojo Chisc	10. FIELD AND POOL, OE WILDCAT Ojo Chiso (Morrow)	
	C, 990' FN	NL & 23	310' FWL				11. SBC., T., B., M., SURVEY OR A 26, T-22-S,		
14. PERMIT	NO			NS (Show whether DF 3435.9' GR	3 (Show whether DF. RT. GR. etc.) 135.9' GR			New Mexico	
16	(	heck A	ppropriate Bo	ox To Indicate N	ature of Notice	, Report, or C	Other Data		
							QUENT REPORT OF :		
TEST W	ATEB SHUT-OFF		PULL OR ALTER	ASING	WATEB SHC	T-OFF	BEPAIRIN	IG WELL	
FRACTU	BE TREAT		MULTIPLE COME	PERTE	PRACTUBE T	REATMENT	ALTERIN	G CASING	
SHOOT ( Repair 7 Other)			ABANDON® CHANGE PLANE	<del></del> -	(NOTE	Report results	ABANDON rf & Frac Mor of multiple completi	row X	
17 DENCRIBE	UROPOSED OR COM	- PLETED OF is directi	ERATIONS (Clean ionally drilled, g	ly state all pertinen give subsurface local	t details, and give	pertinent dates.	letion Report and Log including estimated ai depths for all mar	date of starting any	
5/29/91	MIRU X-per	∙t WS.							
6/6/91				ainer. Set into retaine			Displace oil	mud out of	
6/7/91	Sqz perfs 13141'-44' w/100 sx				ass H. Sting out, Rev out 15 sxs.				
6/8/91	Tag & drill cmt from 13080-86' drill cmt retainer at 13086' and hard cmt to 13190' Fell free, test sqz to 2000 psi OK.								
6/11/91	TIH w/4½" Guiberson Uni-pkr VI on 2-3/8" & 2-7/8" tapered string, set pkr at $13041$ Swab.								
6/12/91	Swab.  TIH w/3-3/4" bit on 2-3/8" & 2-7/8" tbg, tag and drill cmt stringers from 13228 to 13258'. Circ clean.								
6/13/91	Drilling cmt from 13258 to 13294', drill out CIBP at 13294', lwr tbg & bit, tag at 13500', circ clean.								
6/14/91	TIH w/4½"	Guibe	rson RBP 8	& pkr on 2-3	/8" & 2-7/8	' tbg, set	RBP at 13,34	11', 4 hrs swab	
6/15/91	EIR into perfs 13,302-13,328'/unable to pump into perfs @ 5000 psi.								
6/18/91									
6/19/91	POH to 685	50'.							
6/20/91	testing to	\$500	psi w/N <sub>2</sub>	. Well was t	rvina to kie	k and blo	2-3/8" & 2-7 w gas, so sto 45'. (Cont. t	ppped testing	
18. I hereby	certify that the	foregoing	is true and cor	rect					
SIGNED			mson	Pr	oration Ana	lyst	<b>DATE</b>	-5-91	
(This sp	ace for Federal o	r State of	lce use)		Aser	· · · · · · · · · · · · · · · · · · ·			
APPROV CONDIT	ED BY	VAL, IF	<b>ANY</b> :	TITLE			DATE		

\*See Instructions on Reverse Side

•

## RECEIVED

## **JUL** 2 6 1991

Circa HOMA