

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FSL & 660' FWL of Section 7-T22S-R32E (Unit L, NWSW)

5. Lease Designation and Serial No.

NM-84890

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Flamenco Federal #1 SWD

9. API Well No.

30-025-31076

10. Field and Pool, or Exploratory Area

Livingston Ridge Delaware

11. County or Parish, State

Lea  
Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Bradenhead test failed  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-9-95 - Paul Hanes with Yates Petroleum Corporation witnessed bradenhead test scheduled by OCD-Hobbs. Test showed to have a small leak. Notified Bonnie w/OCD-Hobbs that we will repair well.

11-10-95 - Attempt to rig up pulling unit to repair well. Had to shut down due to high winds. Notified OCD-Hobbs (Answering Service) that we will try again on 11-11-95.

11-11-95 - Rigged up pulling unit. TIH and unset packer. TOOH with packer and tubing. TIH w/new packer. NOTE: Hydrotested tubing back in hole. Replaced 2 joints of 3-1/2" tubing and two new collars. Performed mechanical integrity test. NOTE: BLM or OCD did not witness mechanical integrity test.

14. I hereby certify that the foregoing is true and correct

Signed

*Rusty Klen*

Title Production Clerk

Date Nov. 16, 1995

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

**FOR RECORD ONLY**

Title

Date

**NOV 21 1995**