

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-31437	
6. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 220	
9. Pool name or Wildcat ARROWHEAD/GB	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>EAST</u> Line and <u>630</u> Feet From The <u>NORTH</u> Line Section <u>13</u> Township <u>22S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3449 GE	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <u>DRILLING SUMMARY</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU ROD-RIC DRILLING ON 8-25-92, SPUD 12.25" HOLE.
DRILL AND SURVEY TO 1160'.
RUN 8 5/8" CASING TO 1160' AND PUMP 750 SX. CEMENT, CIRCULATED 230 SXs. TO SURFACE.
WAIT ON CEMENT FOR 14.5 HOURS.
DRILL OUT CEMENT AND FLOAT, TEST CASING TO 1000#-OK.
DRILL AND SURVEY TO TD AT 3870'.
RUN 5.5" CASING TO 3870', PUMP 800 SXs. CEMENT AND CIRCULATE 106 SXs. TO SURFACE.
INSTALL WELLHEAD AND TEST-OK.
RELEASE RIG AT 1:00 AM ON 9-1-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 9-3-92

TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON DATE SEP 08 1992
DISTRICT I SUPERVISOR TITLE

CONDITIONS OF APPROVAL, IF ANY: