

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

P. O. BOX 1980
HOBBS, NEW MEXICO 88202-1980
(Other instructions on reverse side)

RM Roswell District
Modified Form No.
NM60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		3a. Area Code & Phone No. 505-622-1127		5. LEASE DESIGNATION AND SERIAL NO. NM-27805	
2. NAME OF OPERATOR Strata Production Company				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1030, Roswell, New Mexico 88202-1030				7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 862' FSL & 458' FWL				8. FARM OR LEASE NAME Lechuza Federal	
				9. WELL NO. #1	
				10. FIELD AND POOL, OR WILDCAT East Livingston Ridge Delaware	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 15-22S-32E	
14. PERMIT NO. 30-025-31495		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3722' GL		12. COUNTY OR PARISH Lea	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Strata Production Company proposes to workover the Lechuza Federal #1 in the following described manner:

1. RU pulling unit. TOH with pump and rod string. Release TA and TOH with tubing.
2. TIH with RBP. Set RBP to perforate and test interval 7140'-7170'.
3. Acidize, swab test and frac, if appropriate.
4. Set RBP to perforate and swab test interval 7180'-7200'.
5. Acidize, swab test and frac, if appropriate.
6. Place well back on production.

Recompletion to be performed on or about June 9-20, 1993.

18. I hereby certify that the foregoing is true and correct

SIGNED Carol J. Garcia

TITLE Production Supervisor

DATE 5/21/93

(This space for Federal or State office use)

APPROVED BY David H. Glass

TITLE PETROLEUM ENGINEER

DATE JUN 16 1993

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

JUN 18 1993

OLD HOBBS
OFFICE