

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

Santa Fe, New Mexico 87504-2088

| | | |
|--|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | API NO. (assigned by OCD on New Wells) 30-025-31534 |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator CHEVRON U.S.A. INC. | | 6. State Oil & Gas Lease No. N/A |
| 3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS | | 7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT |
| 4. Well Location Unit Letter P : 330 Feet From The SOUTH Line and 420 Feet From The EAST Line Section 12 Township 22S Range 36E NMPM LEA County | | 8. Pool name or Wildcat ARROWHEAD/GB |
| 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3442 GE | | |

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: **COMPLETION** ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TIH WITH BIT AND DRILL FLOAT AND CEMENT TO 3800'.
LOG HOLE: GR-CCL, CBL-CET.
PERFORATE 5.5" CASING WITH 4" GUNS, 2 JHPF, 180 DEG. PHSD, 3808-18 & 3688-90, TOTAL OF 24 HOLES.
SWAB TEST PERFS. ACIDIZE PERFS WITH 2 BBLS PER SET OF 15% NEFE.
PERF 3626-3795 WITH 4" GUNS, 2 JHPF, 180 DEG. PHSD. ACDZ WITH 1000 GALS OF 15% NEFE.
SWAB BACK ACID.
PERFORATE 3770-76 AND ACIDIZE WITH 100 GALS. OF 15% NEFE. SWAB BACK ACID.
TIH WITH TBG. AND RODS, EOT AT 3758'.
WELL COMPLETED ON 6-17-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 6-23-92
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____