

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31576
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB 134
7. Lease Name or Unit Agreement Name Kiwi AKX State
8. Well No. 1
9. Pool name or Wildcat East Livingston Ridge Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>P</u> : <u>330</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>22S</u> Range <u>32E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3704' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Perforate & Treat</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforated 7202-8643' w/72 - .42" holes (2 SPF) and treated as follows:
Zone 1) 8594, 96, 8603, 04, 07, 08, 19, 20, 42 and 8643' (20 holes). Acidized w/1000g. 7½% NEFE acid. Frac'd w/2000g. linear pad, 4000g. XL pad, 7500g. XL gel and 28000# 20/40 sand.
Zone 2) 8423, 26, 30, 34, 37, 41 and 8444' (14 holes). Acidized w/ 750g. 7½% NEFE acid.
Zone 3) 7260, 61, 62, 63, 64, 65, 72, 73, 77, 80, 82, 86, 90 and 7291' (28 holes). Acidized w/ 1500g. 7½% NEFE acid. Frac'd w/3000g. linear pad, 5000g. XL pad, 10000g. XL gel and 36000# 16/30 sand.
Zone 4) 7202, 03, 04, 05 and 7206' (10 holes). Acidized w/500g. 7½% NEFE. Frac w/1200g. linear pad, 2400g. XL pad, 4350g. XL gel and 18000# 20/40 sand.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-22-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 27 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 26 1992

OCD HOBBS OFFICE