

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31599
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB 134
7. Lease Name or Unit Agreement Name Kiwi AKX State
8. Well No. 3
9. Pool name or Wildcat East Livingston Ridge Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>H</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>22S</u> Range <u>32E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3768' GR
---	--	--	--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>Production Casing</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
TD 8850'. Ran 208 joints 15.5# and 17# 5-1/2" casing set at 8850'. Float shoe set 8850', float collar set 8808'. DV tool set 7662'. Cemented in 2 stages. Stage 1: 225 sx "H" w/8#/sx CSE, .6% CF-14, 5#/sx Gilsonite, .35% Thriftylite (yield 1.75, wt 13.6). PD 2:05 PM 6-13-92. Bumped plug to 950 psi, held okay. Circulated 64 sacks. Circulated thru DV tool 3 hrs. Stage 2: 780 sx "H" w/8#/sx CSE, .5% CF-14, 5#/sx Gilsonite, .35% Thriftylite (yield 1.82, wt 13.3). PD 6:00 PM 6-13-92. Bumped plug to 3000 psi for 1 minute. WOCU 2 days. Drilled out DV tool at 7662'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 6-26-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 02 '92