

DISTRICT I
P.O. Box 1580, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31644
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-134
7. Lease Name or Unit Agreement Name Kiwi AKX State
8. Well No. 5
9. Pool name or Wildcat East Livingston Ridge Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3728' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>22S</u> Range <u>32E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3728' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-6-92. Perforated 7174-8649' w/118 - .42" holes (2 SPF) and treated as follows:
Zone 1) 8622, 23, 31, 36, 37, 38, 48 and 8649' (16). Acidize w/1000g 7½% NEFE. Frac'd 8622-49' w/9000g 35# XL and 24000# 20/40 sand.
Zone 2) 8435, 37, 39, 43, 62, 63, 64, 65, 73, 76, 79, 83, 91, 99, and 8500' (30). Acidize w/1500g 7½% NEFE. Frac'd 8435-8500' w/14500g. 35# XL and 40000# 20/40 sand.
Zone 3) 7479, 81, 83, 85, 7502, 04, 06, 08, 21, 23, and 7525' (22). Acidized w/1000g. 7½% NEFE. Frac'd 7479-7525' w/18800g. 35# XL and 40000# 20/40 sand.
Zone 4) 7279, 80, 83, 86, 87, 7313, 14, 15, 20, 21, 23, and 7324' (24). Acidized w/1000g. 7½% NEFE. Frac'd 7279-7324' w/13000g. 35# XL and 36000# 16/30 sand.
Zone 5) 7174, 75, 76, 77, 85, 86, 87, 7202, 06, 08, 10, 12 and 7214' (26). Acidize w/1000g 7½% NEFE. Frac'd 7174-7214' w/13000g. 35# XL and 36000# 16/30 sand.
8-10-92. Turn well to production.
8-11-92. First production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-19-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

AUG 21 '92

APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 20 1992

COPIES OF