Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Santa Fe, New Mexico 87504-2088

Form C-103 Revisied 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

1650 Feet From The

Township

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

1. Type of Well:

2. Name of Operato

3. Address of Operator

4. Well Location

Unit Letter

Section

OIL

WELL

P.O. Drawer Dd, Artesia, NM 88210 DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

0, Hobbs, NM 88240	
d, Artesia, NM 88210	API NO. (assigned by OCD on New Wells) 30-025-31674
os Rd., Aztec, Nm 87410	Indicate Type of Lease STATE X FEE
	6. State Oil & Gas Lease No.
	N/A
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lesse Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
(FORM C-101) FOR SUCH PROPOSALS.)	
Vell:	
GAS	
X WELL OTHER	
Perator	8. Well No.
CHEVRON U.S.A. INC.	226
f Operator	9. Pool name or Wildcat
1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	ARROWHEAD/GB

560 Feet From The

NMPM

36E

Range

EAST

County

LEA

11	Check Appropriate Bo	x to indecate	Nature of Notice, Repo	rt, or Other Data		
NOTICE OF	INTENTION TO:		SUBSEC	DUENT REPOR	RT OF:	•
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTER CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OP	NS.	PLUG AND ABAN.	
PULL OR ALTER CASING			CASING TEST AND CMT J	ЮВ		
OTHER:			OTHER: DRILLING	SUMMARY		X
-						

NORTH

3451 GE

10. Elevation(Show whether DF, RKB, RT, GR, etc.)

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.

MIRU ROD-RIC DRILLING ON 8-18-92.

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS

13

SPUD 12 1/4" HOLE ON 8-18-92 DRILL AND SURVEY TO 1210'.

RUN 8 5/8" CASING TO 1210, PUMP 900 SXS. OF CLASS "C" CEMENT, CIRC. 275 SX TO SURFACE. WAIT ON CEMENT FOR 18 HOURS. DRILL OUT CEMENT AND FLOAT, TEST CASING TO 1000#-OK. DRILL AND SURVEY TO 3874, RUN 5 1/2" CASING TO 3874.

PUMP 850 SXS. OF CEMENT AND CIRCULATE 107 SX. TO SURFACE.

INSTALLL WELLHEAD AND TEST.

RELEASE RIG AT 11 AM ON 8-25-92.

TELEPHONE NO	/04E\007 7040
. LEET HORE NO	. (915)687-7812
	# U.S. O. d. 100
DATE	AUG 31'92
	DATE

RECEIVED
AUG 2 8 1992
CO HOBBS OFFICE