Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

N.M. Oil Cons. Division

P.O. Box 1980 Hobbs, NM 88241

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Lease Designation and Serial No.
 NM-2379

	CUMPRY NOTICES AND DEPORTS ON MEN LO		NM-23/9	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			6. If Indian, Allottee or Tribe Name OIF.	
	SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of				
∑ Oil Gas Well Well Other			8. Well Name and No.	
2. Name of Operator			Covington A Fed. #19	
Pogo Producing Company 3. Address and Telephone No.			9. API Well No.	
P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100			30-025-31853 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Red Tank Delaware West	
610' FNL & 660' FEL, Section 26, T22S, R32E			11. County or Parish, State	
			Lea County, NM	
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
	TYPE OF SUBMISSION	TYPE OF ACTIO	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans	
	S	Recompletion	New Construction	
	X Subsequent Report	Plugging Back	Non-Routine Fracturing	
		Casing Repair	Water Shut-Off	
	Final Abandonment Notice	Altering Casing	Conversion to Injection	
		Other Add Delaware Perfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13. Describe direction	e Proposed or Completed Operations (Clearly state a nally drilled, give subsurface locations and measured	Il pertinet details, and give pertinent dates, including estimated dand true vertical depths for all markders and zones pertinent to the	ate of starting any proposed work. If well is nis work.)*	
05/08/9	8 Set RBP @ 7742'. Perf Delaware 7598'	-7606' (1638" dia holes).		
05/09/98 Spot acid across perfs. Perfs broke & went on vacuum.				
05/10/98 Latch onto RBP @ 7742' & reset @ 5106'.			•	
05/11/98	8 Perf Delaware 4944'-58' (2838" dia ho	oles). Acdz w/ 1000 gals 7-1/2% HCL. Swab test.		
05/13/98	8 Run production equipment. Put well on p	oump.		
	10			
4. I hereby	centity that the foregoing is true and correct			
Signed	Idantet And	Title Division Operations Engineer	Date 09/15/98	
(This space	for Federal or State office use)			
Approved b Conditions	y of approval, if any:	Title	Date	
	,,			