

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32128
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B 2656
7. Lease Name or Unit Agreement Name	Hardy 36 State
8. Well No.	1
9. Pool name or Wildcat	South Cass Strawn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Conoco Inc.
3. Address of Operator 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500	4. Well Location Unit Letter <u>K</u> <u>1980</u> Feet From The <u>South</u> Line and <u>2230</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>Lea</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>	
COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>recompletion</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)/SEE RULE 1103.

4-13-98: Move in reverse unit, could not unseat pump, back off rods, POOH, NUBOP, start out, SION.

4-14-98: Finish pulling out of hole w/tubing, GIH w/casing scraper to 8000', POOH, SION.

4-15-98: GIH w/RBP & pkr, set RBP @ 7745', set pkr, test RBP, POOH w/pkr, RUWL, perforate Strawn w/2 SPF from 7562-7570', 7626-64, 7700-7706', start in hole w/work string, testin g in hole to 8000#, SION.

4-16-98: Set pkr @ 7545', RU BJ, pumped 2500 gals acid & ball sealers, reset pkr @ 7495', load backside, SION.

4-17-98: Stimulate Strawn w/25,714 gals 30 quality 20% XL acid & 10,000 gals 20% gelled acid & ball sealers. Opened well.

4-20-98: GIH w/pressure bomb, take reading, POOH w/bomb, GIH w/blanking plug, set plug in profile nipple @ 7495', RD slickline. Release on/off tool. latch on to on/off tool. SION.

4-21-98: G o in hole with 2 3/8" production tubing, GIH w/ 7/8" rods, POOH laying down 7/8" rods, SION.

4-22-98: GIH w/3/4" rods, POOH laying down, POOH laying down 2 3/8" tubing, SION.

4-26-98: Well put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 6-18-98

TYPE OR PRINT NAME Ann E. Ritchie TELEPHONE NO. 915 684-6381

(this space for State Use)

APPROVED BY Ann E. Ritchie TITLE Regulatory Agent DATE 6-18-98

CONDITIONS OF APPROVAL, IF ANY: