

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32728
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2656
7. Lease Name or Unit Agreement Name HARDY 36 STATE
8. Well No. 1
9. Pool name or Wildcat DRINKARD North Hardy Judd R-10327 8/19/94
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator CONOCO INC. 00050735
3. Address of Operator 10 Desta Drive Ste 100 W. Midland, TX 79705	4. Well Location Unit Letter K : 1980 Feet From The SOUTH Line and 2230 Feet From The WEST Line Section 36 Township 20 S Range 37 E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH W/RETRIEVING TOOL. REL RBP. POH WS. RIH W/BIT & SCRAPER TO 6950'. TAG SOLID. POH. RIH W 5 3/4 LEAD BLOCK. POH BLOCK. RIH W/ 3 1/4 SWAGE. 3 1/2 DC. 4 3/4 BUMPER SUB & JARS. 6-4 3/4 DC. TBG. TO 6950'. POH. RIH W 4 1/8 SWAGE- SWAGE TIGHT SPOT. POH. RIH W/ 5 1/4 SWAGE. POH. RIH W/ 6 3/8 SWAGE. POH. RIH W/RBP @ 7254 & PKR @ 6866'. SPOT 100SX ON RET. PCH. RIH W/BIT. DC. 2 3/8 TGB. TAG CMT @ 6595. DO TO 6750. TEST PERFS. CONT DO STRINGERS TO RET @ 6862. DO TO 6960. POH. PERF DRINKARD W/2JSF AS FOLLOWS: 6705-10. 6713-18. 6720-24. 6740-46. RIH W/RBP @ 6999 & PKR @ 6865. TEST HELD. REL PKR & RET RBP. PUH & SET RBP @ 6865. PKR CROSS PERFS-SPOT ACID. PUH SET PKR @ 6610. ACID DRINKARD W/3000 15% HCL-NEFE. REL PKR. RIH. LATCH ON & RET RBP. POH. RIH W/PROD TBG. POH W/ROD STRING 10-19-94. RDMO. 11-17-94 MIRU. REL PKR. POH. RIH W/RET HEAD. LATCH ON REL RBP. POH. RIH W/BIT & SCRAPER. TAG FILL @ 10.270. CO TO 10.307. POH. RIH W/PKR & MCKEE TBG. SET PKR @ 6808. RIH W/VENT STRING & SHORT STRING. RIH W/RODS & PUMP. SPACE MCKEE PUMP. SWAB DRINKARD. O# TBG PRESS W/180# ON CSG. SWAG BACK 116 BBLs WTR. 11-16-94 RDMO. GOING TO PA DRINKARD ZONE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patrick D. Johnston TITLE STAFF REGULATORY ASSIS DATE 1-9-94
TYPE OR PRINT NAME PATRICK D. JOHNSTON TELEPHONE NO. 915-686-6551

(This space for State Use)

Orig. Signed by
Paul Kantz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 20 1995

RECEIVED

JUN 18 1965

RECEIVED
OFFICE