Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALLOF LAND MANAGEMENT

N.M. On Cons. Division

P.O. Box 198() Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

		F LAND MANAGEMEN [
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			Lease Designation and Serial No. NM-2379
			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
I. Type of			
Oil Gas Well Well Other			8. Well Name and No.
2. Name of Operator Pogo Producing Company			Covington A Federal #3
3. Address and Telephone No. P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			9. API Well No.
			30-025-32445
			 Field and Pool, or Exploratory Area Red Tank Delaware
2310' FNL & 1300' FWL, Section 25, T22S, R32E			11. County or Parish, State
 2.	CHECK APPROPRIATE DOV) TO MIDIO TELEVISION	Lea County, NM
- -	TYPE OF SUBMISSION	S) TO INDICATE NATURE OF NOTICE, REPORT, O	R OTHER DATA
		TYPE OF ACTION	
		Abandonment	Change of Plans
	Subsequent Report	Recompletion Plugging Back	New Construction
			Non-Routine Fracturing
	Final Abandonment Notice	Altering Casing	☐ Water Shut-Off ☐ Conversion to Injection
		Other	Dispose Water
. Describe	Proposed or Completed Operations (Clearly st	tate all pertinet details and dive pertinent dates including	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
6/09/98	S. Set CIBP @ 8775'. Perf Delaware 8	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this works are supplied to the supplied of the supplied to the supplin	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
6/09/98	y = == gara resources resources and mage	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this works are supplied to the supplied of the supplied to the supplin	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
)6/09/9 8)6/10/98	S. Set CIBP @ 8775'. Perf Delaware 8	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
6/09/98 6/10/98 6/12/98	3. Set CIBP @ 8775'. Perf Delaware 8 3. Acdz Delaware w/1000 gals 7-1/2%	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as 550'-74' (4838" dia holes). HCL. Swab test. 130'-68' (3838" dia holes).	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
9 <mark>6/09/9</mark> 8 96/10/98 96/12/98 96/15/98	3. Set CIBP @ 8775'. Perf Delaware 8 3. Acdz Delaware w/1000 gals 7-1/2% 3. Set RBP @ 8368'. Perf Delaware 8	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as 550'-74' (4838" dia holes). HCL. Swab test. 130'-68' (3838" dia holes). HCL. Swab test.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
06/09/98 06/10/98 06/12/98 06/15/98	8. Set CIBP @ 8775'. Perf Delaware 8 8. Acdz Delaware w/1000 gals 7-1/2% 8. Set RBP @ 8368'. Perf Delaware 8 9. Acdz 8130'-68' w/ 1000 gals 7-1/2%	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as 550'-74' (4838" dia holes). HCL. Swab test. 130'-68' (3838" dia holes). HCL. Swab test.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
06/09/98 06/10/98 06/12/98 06/15/98 06/17/98	8. Set CIBP @ 8775'. Perf Delaware 8 8. Acdz Delaware w/1000 gals 7-1/2% 8. Set RBP @ 8368'. Perf Delaware 8 9. Acdz 8130'-68' w/ 1000 gals 7-1/2% 9. Frac 8130'-68' w/ 130,000# 16/30 sa	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as th	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) f starting any proposed work. If well is ork.)*
06/09/98 06/10/98 06/12/98 06/15/98 6/17/98 6/18/98	8. Set CIBP @ 8775'. Perf Delaware 8 8. Acdz Delaware w/1000 gals 7-1/2% 8. Set RBP @ 8368'. Perf Delaware 8 9. Acdz 8130'-68' w/ 1000 gals 7-1/2% 9. Frac 8130'-68' w/ 130,000# 16/30 sa 9. Circ well clean. Swab test.	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as th	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) If starting any proposed work. If well is ork.)* ACCEPTED FOR RECORD PETER W. CHESTE JUL 14 1993
06/09/98 06/10/98 06/12/98 06/15/98 06/17/98 06/18/98	8. Set CIBP @ 8775'. Perf Delaware 8 8. Acdz Delaware w/1000 gals 7-1/2% 8. Set RBP @ 8368'. Perf Delaware 8 9. Acdz 8130'-68' w/ 1000 gals 7-1/2% 9. Frac 8130'-68' w/ 130,000# 16/30 sa 9. Circ well clean. Swab test.	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as th	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) If starting any proposed work. If well is ork.)* ACCEPTED FOR RECORD PETER W. CHESTE JUL 14 1393
06/09/98 06/12/98 06/12/98 06/15/98 06/17/98 06/18/98 06/22/98	8. Set CIBP @ 8775'. Perf Delaware 8 8. Acdz Delaware w/1000 gals 7-1/2% 8. Set RBP @ 8368'. Perf Delaware 8 9. Acdz 8130'-68' w/ 1000 gals 7-1/2% 9. Frac 8130'-68' w/ 130,000# 16/30 sa 9. Circ well clean. Swab test.	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as th	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) If starting any proposed work. If well is ork.)* ACCEPTED FOR RECORD PETER W. CHESTE JUL 14 1393
06/09/98 06/12/98 06/15/98 06/15/98 06/17/98 06/18/98 06/22/98	S. Set CIBP @ 8775'. Perf Delaware 8 Acdz Delaware w/1000 gals 7-1/2% Set RBP @ 8368'. Perf Delaware 8 Acdz 8130'-68' w/ 1000 gals 7-1/2% Frac 8130'-68' w/ 130,000# 16/30 sa Circ well clean. Swab test. Run production equipment. Put well	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured and true vertical depths for all markders and zones pertinent to this work as the sured as th	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) If starting any proposed work. If well is ork.)* ACCEPTED FOR RECORD PETER W. CHESTE. JUL 14 1393
06/09/98 06/10/98 06/12/98 06/15/98 06/17/98 06/18/98 06/22/98	Set CIBP @ 8775'. Perf Delaware 8 Acdz Delaware w/1000 gals 7-1/2% Set RBP @ 8368'. Perf Delaware 8 Acdz 8130'-68' w/ 1000 gals 7-1/2% Frac 8130'-68' w/ 130,000# 16/30 sa Circ well clean. Swab test. Run production equipment. Put well ertif that the foregoing is the and correct	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this work as 550'-74' (4838" dia holes). HCL. Swab test. 130'-68' (3838" dia holes). HCL. Swab test. and. Flow well back. I on pump.	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ACCEPTED FOR RECORD PETER W. CHESTE! JUL 14 1993 BUREAU OF LAND MANAGEM, ROSWELL RESOURCE AREA

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



