Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240			WELL API NO.	
DISTRICT II			30-025-32473	
P.O. Drawer DD, Artenia, NM \$2210			5. Indicate Type of Lesse STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410			6. State Oil & Gas Lease No. B-2656	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lesse Name or Unit Agreement Name	
I. Type of Well: OIL X GAS WELL X WELL	OTHER		Hardy 36 State	
2. Name of Operator	LLOT		8. Well No.	
Conoco, Inc. 3. Address of Operator			9. Pool same or Wildcat N. H. A. C.	
10 Desta Drive, Suite 100W, Midlard, Texas 79705			Wildfat Drinkard Tubb	
Well Location				
Unit Letter <u>K</u> : <u>18</u>	<u>6</u> Feet From The SOL	1th Line and 223	30 Feet From The <u>West</u> Line	
Section 36	Township 20S		NMPM Lea County	
	10. Elevation (Show	whether DF, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUB			SEQUENT REPORT OF:	
			SEQUENT HEF ONT OF .	
	PLUG AND ABANDON		X ALTERING CASING	
	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING	ALTERING CASING	
			ALTERING CASING OPNS. PLUG AND ABANDONMENT	
MPORARILY ABANDON		COMMENCE DRILLING	ALTERING CASING OPNS. PLUG AND ABANDONIMENT	
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CEI OTHER:Pulle	X ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB	
MPORARILY ABANDON ULL OR ALTER CASING CHER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. 3/7/96 - MIRU. Bled well jts. tubing, and tag fi	CHANGE PLANS Tions (Clearly sale all periment d 11 down. Pumped 20 111. POOH w/ tubing	COMMENCE DRILLING CASING TEST AND CEL OTHER:Pulle bols. water down ca g, tallied out. RIH	X ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB	
MPORARILY ABANDON	CHANGE PLANS Tices (Clearly sale all periment d 11 down. Pumped 20 111. POOH w/ tubing 6575'. Pulled 84 s and cleaned out to	COMMENCE DRILLING CASING TEST AND CEL OTHER:Pulle bols. water down ca g, tallied out. RIH stands and shut well o 6600'. Latched ont	X ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB	
EMPORARILY ABANDON Image: Completed Oper work) JLL OR ALTER CASING Image: Completed Oper work) 2. Describe Proposed or Completed Oper work) SEE RULE 1103. 3/7/96 - MIRU. Bled well jts. tubing, and tag fi at 6500'. Clean out to	CHANGE PLANS Tions (Clearly state all periment of 11 down. Pumped 20 111. POOH w/ tubing 6575'. Pulled 84 s and cleaned out to 11ar and 212 jts. 2	COMMENCE DRILLING CASING TEST AND CEL OTHER:Pulle bbls. water down ca g, tallied out. RIH stands and shut well b6600'. Latched ont 2-3/8" tubing. NDBOE	X ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB	
EMPORARILY ABANDON Image: Complete of Complete Oper work) 2. Describe Proposed or Complete Oper work) SEE RULE 1103. 3/7/96 - MIRU. Bled well Distribution of the complete of	CHANGE PLANS Tions (Clearly sale all pertinent d 11 down. Pumped 20 111. POOH w/ tubing 6575'. Pulled 84 s and cleaned out to 11ar and 212 jts. 2 es and rig down. Cl	COMMENCE DRILLING CASING TEST AND CEL OTHER:Pulle bbls. water down ca g, tallied out. RIH stands and shut well b6600'. Latched ont 2-3/8" tubing. NDBOE	X ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB	

DISTORED BY	TILE		DATE
(This space for State Use) (2) Classific Area (2000) - Review Weiler - REVION			MAY 02 1996
TYPE OR FRANT NAME Ann E. Ritchie		TELEPHONE NO.	(915) 684–6381
I bereby certify that the information above is true and character to the best of my knowledge as SDONATURE	nd belief. . mile	Regulatory Agent	date04/24/96
And			

CONDITIONS OF APPROVAL, IF ANY.

The states

120 17 cb 2 . 30 31 and the state