(June 1990) DEPARTMENT		O STATES OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals SUBMIT IN TRIPLICATE 1. Type of Well Oil Gas Well Other 2. Name of Operator			5. Lease Designation and Serial No. NM-69376
			6. If Indian, Allottee or Tribe Name
			7. If Unit or CA, Agreement Designat
			8. Well Name and No.
			Federal 27 #6
Pogo Producing Company			9. API Well No.
3. Address and Telephone No. P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100			30-025-32842 10. Field and Pool, or Exploratory Art
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Red Tank Delaware West
1650' FSL & 990' FWL, Section 27, T22S, R32E			11. County or Parish, State
			Lea County, NM
12. CHECK APP			I
		D INDICATE NATURE OF NOTICE, REPORT, O	
TYPE OF SU	BMISSION	TYPE OF ACTION	
Notice of Inte	ent	Abandonment	Change of Plans
Subsequent	Report	Recompletion	New Construction
		Casing Repair	Water Shut-Off
, Final Abandonment Notice		Altering Casing	Conversion to Injection
		X Other Add Delaware Pay	Dispose Water (Note: Report results of multiple completion on We Completion or Recompletion Report and Log form.)
05/15/01 Press csg to 05/16/01 Drld cmt 699 05/17/01 Rel RBP @ 7 05/30/01 Catch & rele: 05/31/01 RIH w/ RBP 06/01/01 Acdz 7712'-3 06/02/01 Latch onto R 06/03/01 Perfs 7412'-2 06/06/01 Resqueeze p 06/07/01 Test csg to 1 06/08/01 Drld cmt 703	10'-50 [°] w/ 150 sks Cl "H" (1000# ok. Tag cmt @ 69)6'-7150'. Test sqz to 1000 7320' & POOH. ase RBP @ 8000'. POOH & set @ 7793'. Test to 30 32' w/ 1000 gals 7-1/2% ac RBP @ 7793' & reset @ 75 20' would not break. Relea perfs 7110'-50' w/ 275 sks 1000# ok. Drld cmt 6800'- 3''-7150'. Test sqz to 1000 20' w/ 750 gals 7-1/2% acid	D# ok. 0 & LD. 00# ok. Perf Delaware 7412'-20' & 7712'-32' w/ 2 spf. id. 42'. Test to 2500# ok. Could not break perfs. Reperf 7 ase RBP @ 7542' & reset @ 7383'. Test to 2000# ok. "H" cmt @ 15.6 ppg. 7037'. D# ok. PU RBP @ 7383', lower & set @ 7575'. Test to	
	egoing is true and correct		
14. I hereby certify that the fore Signed (This space to Conditions of a condi	D'FOR RECORD a.) DAVID R. GLAS 2 5 2001	Title Operation Tech	Date _06/19/01





· · ·