

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-031695B

6. If Indian, Allottee or Tribe Name

7. If Unit or ICA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

Injection

2. Name of Operator

Conoco Inc

3. Address and Telephone No.

10 Dista Dr, Ste 100 W, Midland TX 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL & 1980 FEL

Unit letter G, Sect 29, T20S, R38E

8. Well Name and No.

Warren Unit McKee 110.23

9. API Well No.

30-025-07855

10. Field and Pool, or Exploratory Area

Warren McKee

11. Country or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Squeeze
perfs

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Min Phizer's Floperm 340 gel w/250 BBL fresh water. Pump
Floperm 340 into McKee perfs (8930-8990). After pmpg 183
BBL, the Floperm 340 flash set in the tbq lines & trucks.
AIR 8 BPM at 1000#. Max press 1500#. BHA w/1.7" hydro-blaster
on coil tbq & clean out Floperm 340 gel from surf to 6000.
W/H w/coil tbq & 1.5" hydro-blaster. Lag Floperm at 6000
washed to 6250. Coil tbq stuck increased pmp press & worked
coil tbq free. RU pmp truck break circ & clean out 2 3/8" prod
tbq & to bottom of perfs at 8960. Circ Clean & POH. Miku, RD BOP
& set tbq back in original place. True WH. Return to wtr inj.

14. I hereby certify that the foregoing is true and correct

Signed

Christine Neff

Title

Admin. Assistant

Date

6-28-91

(This space for Federal or State office use)

Approved by

FOR RECORD ONLY

Title

CC

Date

AUG 27 1991