## New Mexico Gil Cornegrossion .....

1625 N. French der Hebbs, NM 82240

Form 3160-5

## **UNITED STATES**

FORM APPROVED

		DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	
	DONEAU OF LAND	MANAGEMENT	Expires: March 31, 1993  5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			NM-2379 6. If Indian, Allottee or Tribe Name
Do not use this form for Use "A	or proposals to drill or to APPLICATION FOR PER	deepen or reentry to a different reservoir. RMIT-" for such proposals	o. I Indian, Another of Tribe Name
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well			
LA Well			8. Well Name and No.
Pogo Producing Company			Covington A Federal #1
3. Address and Telephone No.			9. API Well No. 30-025-33074
P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area
4. Location of vveil (Footage, Sec., T., R., M., or Survey Description)			W. Red Tank Delaware
660' FSL & 660' FEL, Section 25, T22S, R32E			11. County or Parish, State
			Lea County, NM
12. CHECK APPR	ROPRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE, REPORT, C	PR OTHER DATA
TYPE OF SUB	TYPE OF SUBMISSION TYPE OF ACTION		
☐ Notice of Intent	t	Abandonment	Change of Plans
ΓΥΥ		Recompletion	New Construction
Subsequent Re	eport	Plugging Back	Non-Routine Fracturing
Final Abandonn	ment Notice	☐ Casing Repair ☐ Altering Casing	☐ Water Shut-Off
		X other <u>Add Delaware</u> Pay	☐ Conversion to Injection☐ Dispose Water
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
10/02/02 TOH w/ rods, p 10/03/02 Perf Delaware 10/04/02 TIH w/ RBP & 10/05/02 Perf Delaware	pump & tbg. 8394-8426 w/ 1 spf. set @ 8500'. Test to 300 8070-84 w/ 2 spf. @ 8500. PUH to 8300 & sw/ 41,500# SLC 20/40 sar	set. Test to 3000# ok. Acdz 8070-84 w/ 100	work.)*
10/09/02 Frac 8070-84 v 10/14/02 Return well to p	production.		