1			·
Submit 3 Copies to Appropriate District Office	State of New Mexico ropriate Energy, Minerals and Natural Resources Department t Office		Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-33082	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No. V-3527
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OAS OR WELL WELL WELL	OTHER		Red Tank 31 State
2 Name of Operator Pogo Producing Company CONFIDENTIAL		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat
P. O. Box 10340, Midland, TX 79702-7340			Undes E. Red Tank Bone Spring
4. Well Location		· · · · · · · · · · · · · · · · · · ·	Feet From The West Line
Unit Letter::	Feet From the	Line and	rearrow the west Line
Section 31 Township 22S Range 33E NMPM County			
	10. Elevation (Show whethe	er DF, RKB, RT, GR, etc.)	
3758' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUB			SEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS		
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
		OTHER: Spud, Set	Surface, Inter & Prod. Casing
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
Spud & Set Surface Casing - MIRU Nabors 353. Spud @ 1200 hrs CDT 9/23/95. Drilled 14-3/4" hole to 816'. TD reached 0430 hrs CDT 9/24/95. Ran 21 jts <u>10-3/4</u> " 40.5# J-55 ST&C casing. TPGS @ 816'. IFV @ 772'. Howco cmt'd casing w/ 500 sxs Halliurton Lite @ 12.8 ppg followed by 200 sxs Cl "C" + 2% CaCl 9 14.8 ppg. Plug down @ 1030 hrs CDT 9/24/95. Recovered 200 sxs excess cmt. WOC 9-1/4 hrs. Cmt has a compressive strength over 500 psi after 8 hrs. Make cut-off. Weld on wellhead & test to 500 psi. NU BOP's & test to 1500 psi.			
Intermediate Casing - Drilled 9-7/8" hole 816' to 4740'. TD reached @ 2300 hrs CDT 9/28/95. Ran 122 jts 7-5/8" 26.40# N-80 LT&C casing. Float shoe @ 4740. Float collar @ 4706'. Howco cmt'd w/ 870 sxs Halliburton Lite @ 12.4 ppg followed by 100 sxs Cl "C" @ 14.8 ppg. Plug down @ 1400 hrs CDT 9/29/95. Recovered 37 sxs excess cmt. ND BOP's & make cut-off. Weld on wellhead & test to 1500 psi. NU BOP's & test to 1500 psi.			
TD & Production Casing - Drilled 6-3/4" hole to 9010'. TD reached @ 1100 hrs CDT 10/7/95. Logged well w/ Schlumberger. Ran 211 jts 4-1/2", 11.60#, N-80 & J-55 casing. Float shoe @ 9010'. Float collar @ 8965'. Stage tool @ 6360'. Howco cmt'd 1st stage w/ 400 sxs Cl "H" + 5 pps Microbond + 2.4 pps KCl + .6% H322 @ 15.6 ppg. Displace cmt & land plug. Drob bomb & open DV tool. Circulate 5 hrs between stages. Recovered 63 sxs excess cmt. Cmt 2nd stage w/ 380 sxs Cl "C" + 12 pps Gilscnite + 2.8 pps KCl + .3% H332 + .3% H344 @ 14.1 ppg. Plug down @ 0030 hrs CDT 10/9/95. TOC @ 3590'. ND BOP's & make cut-off. Weld on wellhead & test to 2500 psi.			
I hereby cerufy that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Barroth	бе т	me Senior Operat:	ions Engineer DATE 10/26/95
TYPE OR PRINT NAME Barrett L.	Smith	(915)	682-6822 ТЕLЕРНОМЕ NO.
(This space for State Use) State of a State	NED BY JEARY DEXTON IT I SUPPRIVISOR		CCT 8 0 1235
APPROVED BY	π	TLE	DATE