Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Hobbs, NM 88241

N.M. Oil Cons. Division P.O. Box 1980

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

## 5. Lease Designation and Serial No.

NM-96050 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well X Gas Well Oil Well 8. Well Name and No. 2. Name of Operator Gaucho Unit #1 Santa Fe Energy Resources, Inc. 9. API Well No. 3. Address and Telephone No. 30-025-33440 550 W. Texas, Suite 1330, Midland, TX 79701 915/687-3551 10. Field and Pool, or exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) (G), 1650' FNL & 1650' FEL, Sec. 29, T-22S, R-34E Wildcat 11. County or Parish, State NM Lea CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE QTHER DATA 12. TYPE OF SUBMISSION Notice of Intent Abandonment Recompletion SEP 0 6 1995 Subsequent Report Houtine Fracturing Plugging Back Casing Repair Final Abandonment Notice 1187. 6 NA Altering Casing Other 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If so directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* TD 4-1/2" hole at 15,100'. Circ bottoms up. POOH to log & SLM. 8/21/96: LD motor. RU loggers. Logging. 8/22/96: Logging. Circ & WO FMS logging tool. 8/23/96: POOH to run log. 8/24/96: POOH. RU Schlumberger FMS. TIH. Log. Circ bottoms up. POOH. RU casing and PU machine, running liner. 8/25/96: Ran total of 34 jts 3-1/2" 9.3# N-80 F/45 liner and set at 15,098', FC @ 15,062. Top of liner at 13,978'. Cemented w/ 100 sx Cl "H" containing 0.4% CFR-3, 0.6% Halad-9, 5 pps KCl, and .25% HR-7. Plug down at 3:00 p.m. Set top pkr and RD cementing head. Pull 35 stds. Circ btms up. POOH w/ setting tool. 8/26/96 Finsish POOH w/ setting tool. Install rotating head. Circ btms up. WOC. Cut drlg line. TIH, tag cmt @ 13,690'. Drld cmt, tag liner top at 13,978'. POOH. RU Computalog. 1st run - run gauge ring. 2nd run - set Baker 7-5/8" RBP @ Test 7-5/8" csg to 500 psi, ok. TIH w/ BHA & 2-7/8" drill pipe. RU LD mach, LD BHA 11.476'. & DP. 8/28/96: LD DP. RD LD mach. ND BOP, install blank cap. Jet & clean pits. Rig released at 6:00 p.m. Waiting on completion unit.

14. (hereby certify that the foregoing is true and correct Signed Walland	Title Sr. Production C	Clerk Date August 29, 1996
(This space for Federal or State office use)  Approved by  Conditions of approval, if any:	Title	ACCEPTED FOR RECORD  SEP 2 4 1996
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing or representations as to any matter within its jurisdiction.	gly and willfully to make to any department  * See Instruction on Reverse Side	or agency of the United States any false, Geltious of fraudulent statements