

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NM-69372

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340, Midland, TX 79702-7340 (915)682-6822

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 990' FEL, Section 7, T22S, R32E

8. Well Name and No.

E. Livingston Ridge Unit#1

9. API Well No.

30-025-33650

10. Field and Pool, or Exploratory Area

E. Liv. Ridge Delaware

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/15/96 Ran CBL. TOC @ 5880'. Perf 4 - .50" sqz hole @ 5850' & 4200'. Set cigr @ 5783'.

11/16/96 RU Howco. Cmt thru sqz holes @ 5850' w/ 850 sxs Cl "C" + 12 pps Gilsonite + 2.8 pps KCL + .3% H322 @ 14.1 ppg. Sting out of cigr. Pull EOT to 4304'. Pump into sqz holes @ 4200' & circ out 300 sxs excess cmt to surface. WOC 4 hrs. Set RCR @ 4016'. Cmt thru sqz holes @ 4200' w/ 1950 sxs Halliburton Lite @ 12.4 ppg followed by 100 sxs Cl "C" @ 14.8 ppg. Circ 350 sxs excess cmt to surface.

11/17/96 RIH w/ 4-3/4" bit & DC's. D/O cmt & cigr @ 5783'. C/O to PBTD @ 7322'. POOH & LD bit & DC's.

14. I hereby certify that the foregoing is true and correct

Signed

Barnett Smith

Title

Senior Operations Engineer

Date

12/9/96

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date