ubmit 3 Copies) Appropriate istrict Office	State of New Mex. Energy, Minerals and Natural Res	ico ources Department		Form C-103 ' Revised 1-1-89	
ISTRICT I O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503		WELL API NO. 30-025-33683 5. Indicate Type of Lesse STATE FEE X		
ISTRICT II O. Drawer DD, Artesia, NM 88210					
<u>ISTRICT III</u> 2000 Rio Brazos Rd., Aztec, NM 8741	0			6. State Oil & Gas Lesse No.	
(DO NOT USE THIS FORM FOR F DIFFERENT RES	DTICES AND REPORTS ON WELL PROPOSALS TO DRILL OR TO DEEPEN O SERVOIR. USE "APPLICATION FOR PERM M C-101) FOR SUCH PROPOSALS.)	R PLUG BACK TO A	7. Lease Name o	r Unit Agreement Name	
Type of Well: OIL GAS WELL X WELL [OTHER		Кут	te	
Name of Operator			8. Well No.		
Stevens & Tull Address of Operator		- <u> </u>	9. Pool name or		
	5, Midland, TX 79702	· · · · · · · · · · · · · · · · · · ·	DK A	Abo	
Well Location Unit Letter H :	1980 North	Line and6	60 Fest From	n The Line	
23	205	38E		ea County	
Section	Township Rang	· · · · · · · · · · · · · · · · · · ·			
	Appropriate Box to Indicate N NTENTION TO:	SUB	SEQUENT F		
NOTICE OF II RFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Set Su d give pertinent dates, inc d g g g g g g g g g g g g g g g g g g g	SEQUENT F	REPORT OF: ALTERING CASING PLUG AND ABANDONMENT g g c of starting any proposed 24# J-55 casing plus 2% CaCl plus cement to surface.	
NOTICE OF II RFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Derations (Clearly state all pertinent details, and ud well at 9:45 a.m dr: surface hole at 1625'. I 1612'. Cement with lead i1 - 200 sx "c" plus 2% Ca C 18 hours before drilling	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Set Su d give pertinent dates, incl ill 12 1/4" ho Run 38 joints - 615 sx "c" aC1 ₂ - circula g out - instal g 7 7/8" hole.	SEQUENT F	REPORT OF: ALTERING CASING PLUG AND ABANDONMENT g g c of starting any proposed 24# J-55 casing plus 2% CaCl plus cement to surface. est to 3,000 psi -	
NOTICE OF II RFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Derations (Clearly state all pertinent details, and ud well at 9:45 a.m dr: surface hole at 1625'. 1612'. Cement with lead i1 - 200 sx "c" plus 2% C: C 18 hours before drilling sted good - start drilling means complete to the best of my toowledge and belief "Macanang"	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Set Su d give pertinent dates, incl ill 12 1/4" ho Run 38 joints - 615 sx "c" aC1 ₂ - circula g out - instal g 7 7/8" hole.	SEQUENT F	REPORT OF: ALTERING CASING PLUG AND ABANDONMENT g	



2