

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural ResourcesFORM C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.

30-025-33706

5. Indicate Type of Lease

☐ STATE☒ FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

PAYDAY

8. Well No.

1

9. Pool name or Wildcat

BLINEBRY / WARREN TUBB

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

☒ OIL WELL☐ GAS WELL☐ OTHER

2. Name of Operator

Apache Corporation

3. Address of Operator

2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400

4. Well Location

Unit Letter L : 1980' Feet From The S Line and 660' Feet From The W Line
Section 24 Township 20S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3570' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ Perform Remedial Work☐ Plug and Abandon☐ Temporarily Abandon☐ Change Plans☐ Pull or Alter Casing☐ Other☐ Remedial Work☒ Altering Casing☐ Commence Drilling Operations☐ Plug and Abandonment☐ Casing Test and Cement Job☒ Other

DHC #0009 - BLIN /WARREN TUBB

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/28/01 MIRU. KILL WELL. NIPPLE DOWN WELLHEAD.

3/02/01 NIPPLE UP BOP. LONG STRING WILL NOT COME FREE. PREP TO FREE POINT.

3/05/01 RUWL. TBG STUCK @6454'. POH. RIH W/STRING, SHOT & BACK OFF TBG @6146'. RDWL.

3/07/01 RIH BIT & SCAPER. CO FILL TO 6880'. PU RBP & PKR. PREP TO ACIDIZE.

3/13/01 RU PETROPLEX. TEST LINE TO 4000#. ACIDIZE BLINEBRY (5982' - 6100') & WARREN TUBB (6488' - 6814')
W/6500 GALS 15% BXDX IN 2STAGES, W/5000# ROCK SALT.FLUSH W/35 BBLS 2% KCL.

3/14/01 TRIP IN HOLE & TAG SAND @6700', CO FILL TO 6827'.

3/15/01 RIH TAG FILL @6877' PREP TO RUN PRODN EQUIPMENT

3/16/01 RIH W/ 2-3/8" TBG & SN. SN @6850', TAC @5945'. NIPPLE UP WELLHEAD.

3/21/01 HOOK UP FLOWLINE & RETURN WELL TO PRODUCTION. DHC PERMIT #0009 - BLINEBRY & WARREN TUBB

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

SR. ENGINEERING TECH

DATE

6/22/2001

TYPE OR PRINT NAME

FRANCES M. BYERS

TELEPHONE NO.

(713) 296-6361

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: