## State of New Mexico

Suhmit 3 copies to Appropriate District Office	1	Er , Minerals and Nat	tural Resources De	epartment			m C-103
DISTRICT I	0	II CONCEDIA	AMYONINA	TOTON		Re <sup>i</sup>	/ised 1-1-89
P.O. Box 1980, Hobbs, N	M 88240	IL CONSERVA	ATION DIV	ISION	WELL API NO.		
DISTRICT II	VI 00240	P.O. Bo	x 2088			30 025 33782	
P.O. Box Drawer DD, Artes	sia. NM 88210	Santa Fe, New N	/lexico 87504-2	088	5. Indicate Type		
DISTRICT III	,					STATE [	FEE 🔀
1000 Rio Brazos Rd., Azte	c, NM 87410				6. State Oil / Gas	s Lease No.	
S	UNDRY NOTICE	S AND REPORTS OF	N WELL	·			
(DO NOT USE THIS FOI DIFFE	EEPEN OR PLUG I FOR PERMIT (LS.)	BACK TO A	7. Lease Name (	or Unit Agreement Nam SON	ne		
Type of Well: OIL WELL	GAS WELL	OTHER					
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.					8. Well No.	16	
3. Address of Operator	205 E. Bender, H	OBBS, NM 88240			9. Pool Name or \		
4. Well Location						Drinkard	
Unit Letter	E : 16	50 Feet From The	NORTH Line and	d <u>660</u>	Feet From The	WEST Line	
Section 30	То	wnship 21-S	Range <u>37-E</u>	NM	IPM	LEA COUN	ΓY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3499'							
11.	Check Appro	priate Box to Indica	te Nature of No	tice, Report	. or Other Dat	la	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:							
		G AND ABANDON	DEMEDIAL I				
PERFORM REMEDIAL WOR	` ⊔		REMEDIAL			LTERING CASING	∐
TEMPORARILY ABANDON CHANGE PLANS				COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT			
PULL OR ALTER CASING			_	ST AND CEMEN	لجا		
OTHER:			L OTHER:		Comple	etion	
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</li> </ol>							
3-8-97: Perforate Drinkard Zone w/2jspf 6644'-6700' (7252" holes). SI. 3-9-97: TIH w/packer and set @ 6489'. Acidize perfs 6644'-6700' w/5000 gals NEFE in 3 stages. Max Pres 4700 psi, Min Pres 1525 psi, Avg Pres 3250 psi, ISIP 1020 psi, avg rate 4.0 BPM. SI							
3-10-97: Tbg pres on vacuum, swabbing. SI 3-11-97: Release packer, POH. Run production equipment. SI 3-12-97: Tbg set @ 6762'. Remove BOP. SI							
3-13-97: Run pump & rods. RD. SI. 3-14-97 thru 3-17-97: Wait on electric.							
3-18-97 thru 4-1-97: Pumping & testing 4-2-97: OPT: 8-BO, 30-BW, 22-MCF							
·							

I hereby certify that the information above is true and compley SIGNATURE	to the best of my knowledge and belief.  TITLE Engineering Assistant	DATE <u>10/3/97</u>
TYPE OR PRINT NAME Paul	la S. Ives	Telephone No. 397-0432
(This space for State Use) ORIGINAL SIGNE APPROVED BY GARY WINF		DATE UCL 1 = 1807
CONDITIONS OF APPROVAL FIELD REP.		