

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025--33880
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	M & M
8. Well No.	3
9. Pool name or Wildcat	Blinebry Oil & Gas (06660)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Collins & Ware, Inc.	
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>24</u> Township <u>20S</u> Range <u>38E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3571 GL 3581 KB 3580 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Perforate and treat ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/25/97 Set CIBP at 6883' and dumped 4 sx cement on top of plug. Set CIBP at 6510'. Perforate Blinebry 5951' - 62', 6010' - 30', 6073' - 78', 6094' - 99' with 1 SPF and total of 41 perfs. Dumped 4 sx cement on plug at 6510'. PBTD at 6470'.

7/27/97 Set packer at 5840' and acidize perfs with 2500 gals 15% Ferchek SC acid.

7/30/97 Frac well with 50,000 gals Delta-Frac 25 carrying 140,000# 20/40 Ottawa sand. TIH with 2 3/8" tubing and set packer at 5875'. Will start testing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE 8/8/97

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use)

Orig. Signed by  
Paul Rantz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 15 1997

CONDITIONS OF APPROVAL, IF ANY: