(June 1990) DEPARTM	ITED STATES ENT OF THE INTERIOR		FORM APPROVED Budget Burcau No. 1004-0135
	F LAND MANAGEMENT	N.M. Oil Cons	Expires: March 31, 1993
	AND REPORTS ON WELLS		
Do not use this form for proposals to d	fill or to deepen or reentry to a diff	Hobbs, NM 882	16. If Indian, Allottee or Tribe Name
Use "APPLICATION FO	DR PERMIT - " for such proposals		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Other Other			8. Well Name and No.
2. Name of Operator Santa Fe Energy Resources, Inc.			-Gaucho Unit No. 2-
3. Address and Telephone No. 550 W. Texas, Suite 1330, Midland, TX 79701915/687-3551			9. API Well No. Not assigned
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or exploratory Area
(K), 1650' FSL and 1725' FWL, Sec. 29, T-22S, R-34E			North Bell Lake (Morrow 11. County or Parish, State
2. CHECK APPROPRIATE BOX	(S) TO INDICATE NATURE OF	NOTICE, REPORT O	Lea NM
TYPE OF SUBMISSION		TYPE OF ACTION	
Notice of Intent	Abandonment		Change of Plans
X Subsequent Report	Recompletion		New Construction
	Plugging Back		Non-Routine Fracturing
Final Abandonment Notice			Water Shut-Off
	Altering Casing	<u>circ & ran csg</u>	Conversion to Injection
		encardnicsg	[] Dispose Water (Note: Report results of multiple completion on Well
Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true ve	all pertinent details, and give pertinent dates, include	ding estimated date of starting at	Completion or Recompletion Report and Log form.)
4/14/97: Drilled 12-1/4" hole to R&M, ran FPI & backoff DCs @	3684'. Lost circ & PUH 19 std	s w/100K drag	
4/15/97: TIH. Tag fish & workov TIH BHA. Cut drlg line. TIH w/E Wash 1860-1984', lost circ, pull	PP. PU kelly, screw in fish, PC	POH. LD 2 jts wip DH. LD fish tools.	er, PU jars & BS. TIH, tag fill @ 1860'.
4/16/97: Mix & pmp 300 bbl LC regain, wash 1984'. Wash 1984 2294' & stuck @ 2309'. Spot die	-21/1.Circ & mix 400 bbl mu	pe. TIH, tag 1877', d losing 50 BPH, lg	drill bridge, loss circ, vol sand. Wash to
regain, wash 1984 . Wash 1984	-21/1'. Circ & mix 400 bbl mu sel & work stuck string. 60 bbl diesel w/pipe free & wo	d losing 50 BPH, Ig rk string Run FPI	vol sand. Wash to
2294' & stuck @ 2309'. Spot die 4/17/97: Work stuck pipe. Spot Work stuck pipe & PU 1st driving oil on spot.	-21/1'. Circ & mix 400 bbl mu sel & work stuck string. 60 bbl diesel w/pipe free & wo	d losing 50 BPH, Ig rk string Run FPI	vol sand. Wash to stuck 1830-62'. tring w/driving tool &
2294' & stuck @ 2309'. Spot die 4/17/97: Work stuck pipe. Spot Work stuck pipe & PU 1st driving oil on spot.	-21/1'. Circ & mix 400 bbl mu sel & work stuck string. 60 bbl diesel w/pipe free & wo	d losing 50 BPH, Ig rk string. Run FPI, tring. Work stuck s (Cont. on 1	vol sand. Wash to stuck 1830-62'. tring w/driving tool &
 1984. Wash 1984. Wash 1984. 2294' & stuck @ 2309'. Spot die 4/17/97: Work stuck pipe. Spot Work stuck pipe & PU 1st driving oil on spot. 	-21/1'. Circ & mix 400 bbl mu sel & work stuck string. 60 bbl diesel w/pipe free & wo tool & twist pin. Work stuck s	d losing 50 BPH, Ig rk string. Run FPI, tring. Work stuck s (Cont. on 1 Clerk	vol sand. Wash to stuck 1830-62'. tring w/driving tool & Page 2)
 1984. Wash 1984. Wash 1984. 2294' & stuck @ 2309'. Spot die 4/17/97: Work stuck pipe. Spot Work stuck pipe & PU 1st driving oil on spot. 	-21/1'. Circ & mix 400 bbl mu sel & work stuck string. 60 bbl diesel w/pipe free & wo tool & twist pin. Work stuck s	d losing 50 BPH, Ig rk string. Run FPI, tring. Work stuck s (Cont. on 1	vol sand. Wash to stuck 1830-62'. tring w/driving tool & Page 2)
 1984. Wash 1984. Wash 1984. 2294' & stuck @ 2309'. Spot die 4/17/97: Work stuck pipe. Spot Work stuck pipe & PU 1st driving oil on spot. Thereby certify the the foregoing is the and correct signed. Thereby certify the the foregoing is the and correct signed. This space for Federal or State office use) Approved by	60 bbl diesel w/pipe free & wo tool & twist pin. Work stuck s	d losing 50 BPH, Ig rk string. Run FPI, tring. Work stuck s (Cont. on 1 Clerk	vol sand. Wash to stuck 1830-62'. tring w/driving tool & Page 2)

amonth high