

1 Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-34060
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Sharps
8. Well No.	1
Pool name or Wildcat	South House Blinbry Oil & Gas (06660)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Collins & Ware, Inc.

3. Address of Operator
508 West Wall, Suite 1200, Midland, Texas 79701

4. Well Location
Unit Letter M : 787 Feet From The South Line and 660 Feet From The West Line
Section 13 Township 20S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3575' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Set Casing, perf and stimulate ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/11/97 TD at 7225'
9/12/97 Ran Platform Express with NGT. Ran 5 1/2" casing to 7224' and cement with a total of 1500 sx cement.
9/14/97 Ran Gamma Ray, CCL log from PBTD 7094' to 3500'. Perf total of 48 holes using 1 SPF 4" casing gun at 5976' - 5984', 6030' - 6050', 6086' - 6106'.
9/15/97 Set RBP at 6143' and packer at 6106'. Spot 200 gals 15% HCl acid across perfs 5976' - 6106'. Set packer at 6074'. Acidize perfs 6086' - 6106' with 100 gals 15% HCl acid with ball sealers. Set RBP at 6074' and packer at 6011'. Acidize perfs 6030' - 6050' with 1000 gals 15% HCl acid with ball sealers. Set RBP at 6011' and packer at 5916'. Acidize perfs 5976' - 5984' with 600 gals 15% HCl acid with ball sealers.
9/16/97 POH with tubing and packer and plug. Frac well down 5 1/2" casing with 54,000 gals Delta-Frac and 163,000 # 20/40 Ottawa sand. RIH with 2 3/8" tubing to 6412'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE 9/22/97

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use)

Orig. Signed by
Paul Kautz
Generalist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 07 1997