

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-34275
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Pearl
8. Well No.	1
9. Pool name or Wildcat	ABO/South; Blinbry, South
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3553 GR 3566 DF 3567 KB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Collins & Ware, Inc.
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	4. Well Location Unit Letter J : 2030 Feet From The South Line and 2000 Feet From The East Line Section 13 Township 20S Range 38E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3553 GR 3566 DF 3567 KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Drill out CIBP <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/13/98 Pull rods, pump, and tubing.

5/14/98 Go in hole with sand line drill bailer. Tag sand at 7285'. Drill and bail and recover sand and ball sealers off of CIBP. Move CIBP down 7'.

5/15/98 Top of CIBP at 7300'.

5/16/98 Drill on CIBP and fell through. Chase plug to PBDT at 7777'. Run 2 7/8" tubing to 7532', SN at 7497', and anchor at 5827'. Go in hole with 2 1/2" x 1 1/2" x 24" RHBC pump. Put well on production.

DHC-1996

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Administrator DATE 6/12/98

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. (915) 687-3435

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

GW  
JC