

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

| | |
|--------------------------------------|--|
| WELL API NO. | 30-025-34286 |
| 5. Indicate Type of Lease | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. | |
| 7. Lease Name or Unit Agreement Name | Hansen State |
| 8. Well No. | 9 |
| 9. Pool name or Wildcat | Monument: Abo, SE |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | |
| 2. Name of Operator Marathon Oil Company | |
| 3. Address of Operator P.O. Box 2409 Hobbs, NM 88240 | |
| 4. Well Location Unit Letter <u>H</u> : <u>2190</u> Feet From The <u>North</u> Line and <u>460</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>20-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3544' KB 3557' | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Place well on rod pump. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16 MIRU pulling unit. ND wellhead. NU BOP. Test, OK. TIH w/whipstock retriever. POOH w/whipstock. RIH w/bit to CIBP. DO CIBP and push to PBTD at 7790'. POOH.
7/19 Perf 7060-7068' w/2 SPF, 17 holes. RIH w/RBP & pkr. Set at RBP at 7100', pkr at 7020'. Acidize w/2000 gals 20% acid. Start well flowing.
7/22 RIH, rel pkr, latch onto RBP, POOH w/both. TIH w/2 3/8" prod tbg. ND BOP. Set TAC. NU wellhead. Hot oil tbg. RIH w/pump & rods. Load & test, OK.
7/24 RD pulling unit. Clean location.

TAC at 6972'.
SN at 7306'.
End of tbg 7336'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 7/28/99
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 05 1999

CONDITIONS OF APPROVAL, IF ANY:

SC