

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-34629
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. Lease Name or Unit Agreement Name Bell Lake Unit	
2. Name of Operator Santa Fe Snyder Corp.		8. Well No. 20	
3. Address of Operator 550 W. Texas, Suite 1330, Midland, TX 79701		9. Pool name or Wildcat Ojo Chiso (Morrow)	
4. Well Location Unit Letter E : 1650 Feet From The North Line and 660 Feet From The West Line Section 32 Township 22S Range 34E NMPM Lea County		10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3424' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/21/99

TD 17½" @ 2a.m. Circ for csg. POH, LD BHA. RU csg crew & LD machine. Ran 53 jts 13-3/8" 61# J-55 STC csg. RU BJ. Circ for cmt. Ctm w/850 sx 50-50-10 followed by 300 sx "C" + 2% CaCl. Circ 400 sx. WOC, clean pits. ND 20" BOPs, cut 20" & 13-3/8". Weld on 13-3/8" SOW x 13-3/8" 3K braden head. Install 13-3/8" 5000 BOP.

9/22/99

NU BOP & cross. PU BHA, TIH DCs. Test BOP. Repair #2 pump. TIH. Drl plug, float & cmt. Attempt test csg, BOP would not hold. POH. Change out BOPs.

9/23/99

NU BOP. TIH DCs. Test csg & BOP to 500 PSI, ok. Drl to shoe. Drl new 12¼" hole @ 3:45am.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 10/21/99

TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/686-6612

(This space for State Use)

ORIGINAL SIGNED BY  
GARY WINK

OCT 29 1999

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: