

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34669
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W. T. MCCOMACK
8. Well No. 19
9. Pool name or Wildcat TUBB OIL & GAS (PRO GAS)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Chevron U.S.A. Inc.	
3. Address of Operator P.O. Box 1150, Midland, TX 79702	
4. Well Location Unit Letter <u>P</u> <u>790</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3458'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: <u>COMPLETED</u> ☒
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

DRLD CMT & DV TOOL TO 5355'. WASHED TO 5369'. TSTD CSG 600 PSI-HELD 15 MIN. DRLD CMT TO 7490'.
PERFD 7327'-7382' W/4 JHPF. ACZD W/5000 GALS 15% & 250 RCNB'S. SWABBED. SET CIBP @ 7320', W/10' CMT
ON TOP. PERFD 7214'-7262' W/4 JHPF. RAN TS. PPD 100 SX CL "C" @ 6668'; OBTAINED 2000 PSI SQZ - TOC 6836'.
DRLD CMT TO 7270'; WASHED TO 7310' - TSTD 500 PSI/HELD OK 30 MIN. PERFD 7214'-7262'. SWABBED. DRLD CMT
& CIBP; PUSHED TO 7490'. CIRC CLEAN. PPD 100 SX CL "C" @ 6998'; TSTD SQZ 1000 PSI-HELD OK 15 MIN. PPD
100 SX CL "C" @ 6814'; TOC 7024'. DRLD CMT TO 7243'. CIRC CLEAN - TSTD 500 PSI/HELD OK 10 MIN. PERFD
7214'-7237'. SWABBED. SET CIBP @ 7200' W/24' CMT ON TOP. PERFD 6716'-6721'. TSTD CSG & CIBP TO 500
PSI-HELD OK. ACZD W/5000 GALS 20%. SET RBP @ 6685' W/300# SAND ON TOP - 6664'. PERFD 6038'-6246'.
ACZD W/3500 GALS 15% & 180 RCNB'S. FRACD W/68,500 GALS FOAM & 492,320# SAND. RIH W/TBG TO 5964'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 12/7/99
TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: