

Proposed Well Plan

State "A" A/C 2, Well # 77

660' FSL & 560' FEL, Sec. 8, T 22S, R 36E, Unit Ltr 'P', Lea Co.

1. Drill 12 ¼" hole from surface to 600'.
2. Run 8 5/8" 24# casing to 600' cement W/ 240 sx cement with additives to Surface.
3. Drill 7 7/8" hole to 3900'.
4. Run 5 ½" 15.5# casing to 3400' cement W/ 490 sx cement with additives to surface.
5. Perforate the Queen formation from 3600' to 3890'
6. Perforate the 7 Rivers (Oil) formation from 3426-3607' (if Queen not Productive)
7. Acid and Frac treatment will be determined after looking at the Logs.
8. Complete and put on production.

