Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re		Form C 103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM S8240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-34910	
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease	
DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM (	ICES AND REPORTS ON WEI OPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE •APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Oil Sas Well Gas Well	OTHER		State A A/C 2	
2. Name of Operator		8. Well No.		
Raptor Resources, Inc.			78	
3. Address of Operator			9. Pool name or Wildcat Eunice: Seven Rivers-Queen, South (24130)	
901 Rio Grande, Austin, TX 4. Well Location	78701		Eunice. Seven Rivers Queen, South (21156)	
Unit Letter <u>E</u> 1980	) Feet From The North	Line and 60	50 Feet From The West Line	
Section 5			NMPM Lea County	
N/////////////////////////////////////	10. Elevauon (Show <i>whether</i>		///////////////////////////////////////	
11 Check	Appropriate Box to Indicate	Nature of Notice, R	leport, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			SEQUENT REPORT OF:	
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
		OTHER	Squeeze Lower Perfs	

10/11/00 MIRU. POOH W/ 2 3/8" tbg & pump. GIN W/ 5 1/2" RBP set @ 3604'. Perf the Jalmat 7 Rvrs Reef W/ 2 SPF @ 3455', 3479', 3484', 3492', 3499', 3512', 3536', 3.562', 3570', 3586', 3593' and 3597' for a total of 24 holes. GIH W/ 2 3/8" tbg & 5 1/2" packer set @ 3346'.

10/18/00 Shut in well for further evaluation.

10/28/00 RU. Lower RBP to 3725', spot 2 sks sand on RBP. GIH W/ tbg & AD-1 Pkr. Run 5 1/2" cement retainer set @ 3416', test tbg to 1000# & retainer to 500#. Sting into retainer pump 200 sks Class "C" neat W/ 2% CaCl to squeeze perfs from 3455 to 3711'. Final squeeze pressure @ 85#, stung out of retainer & reversed 35 sks. SI WOC.

10/31/00 GIH W/ 4 3/4" bit & 6 3 1/2" drill collars on 2 3/8" tbg. Drill out retainer & hard cement to 3422', circ hole clean. Continue drilling out cmt. Tested squeezed perfs to 500# @ 3504', 3575' & 3725', washed 4' of sand off RBP, circ hole clean, POOH. GIH W. releasing tool on 2 3/8" tbg, latched onto & released RBP @ 3725', POOH. GIH W/ 109 jts 2 3/8" tbg set @ 3499' and set Sub pump. 11/18/00 RDMO. Returned well to production, producing from perfs @ 3730' to 3912'.

12. Thereby certify that the information above is true and complete to the best of my knowledge and belief	DATE 12/3/00
SIGNATURE SIGNATURE TITLE -	TELEPHONE NO. 915-697-1609
(this space for State Use)	
APPROVED BY	 DATE