

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002535593
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEIR C. H. -B-
8. Well No.	12
9. Pool Name or Wildcat	UMONT YATES 7 RIVERS QUEEN (PRORATED GAS)
10. Elevation (Show whether DF, RKB, RT GR, etc.)	3752' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>J</u> : <u>1650</u> Feet From The <u>SOUTH</u> Line and <u>1650</u> Feet From The <u>EAST</u> Line Section <u>11</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT GR, etc.)	3752' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO INTENDS TO PLUG AND ABANDON THE SUBJECT WELL. VERBAL APPROVAL TO PROCEED WAS GIVEN TO CHARLIE AUPIED WITH CHEVRONTXACO BY MR. GARY WINK WITH THE NMOCD ON 11/6/01. THE INTENDED PROCEDURE IS AS FOLLOWS:

- 1) RUN BIT IN HOLE ON 2 7/8" USED TBG TO TOP OF FISH AT 3133'.
- 2) CIRC HOLE. SPOT CMT PLUG FROM TOP OF FISH TO 2000'. USE 380 SACKS CL C + 0.1% D65 DISPERSANT. NO NEED TO TAG PLUG.
- 3) PULL OUT OF HLE TO 561'. STAND TBG BACK IN DERRICK UNTIL TOP OF CMT PLUG IS CLEARED.
- 4) CIRC & SPOT CMT PLUG ACR 8 5/8" CSG SHOE FR 561'-361'.
- 5) PICK UP ABOVE CMT & WAIT ON CMT 6 HRS.
- 6) TAG CMT PLUG.
- 7) LAY DOWN TBG.
- 8) ND BOPS. INSTL DRY HLE FLANGE.

THE OPERATOR MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CLOSING TO BE APPROVED.

8 5/8" 24#/FT SURF CSG SET @ 46'
CMT W/300 SX CL C + 2% CACL
CIRC 16 BBLS CMT TO SURF
7 7/8" OPEN HOLE DRILLED TO TD @ 4000'.

FISH LEFT IN HOLE: BIT, BIT SUB, 2' DC'S, 1 JT OF DP (TOTAL=641') TOP OF FISH @ 3133'. BTM OF FISH @ 3774'

PLUG - 380 SACKS FR 3133-2000 (FROM TOP OF FISH UP INTO THE SALT)
100 SACKS FR 561'-361' (100' ABOVE & BELOW THE 8 5/8" SHOE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/8/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED 80 CONDITIONS OF APPROVAL IF ANY: DATE

IC

dm