

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002535593
5. Indicate Type of Lease:	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEIR, C. H. -B-
8. Well No.	12
9. Pool Name or Wildcat	EUMONT YATES 7 RIVERS QUEEN (PRORATED GAS)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>J</u> : <u>1650</u> Feet From The <u>SOUTH</u> Line and <u>1650</u> Feet From The <u>EAST</u> Line Section <u>11</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3752' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	COMPLETION DATA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-24-01: MIRU KEY RIG.
10-25-01: RIG REPAIR - WAIT ON CATHEADS.
10-27-01: SPUD WELL @ 1915 HRS 10/26/01. DRILLING 262' - 461'.
10-28-01: TIH W/8 5/8" J-55 24#/FT CSG, 10 JTS, FC, & GUIDE SHOE. TOTAL-461.12'. CIRC. CMT SURF CSG W/300 SX CL C + 2% S1. DISPL W/27.6 BFW. PLUG DOWN @ 11:30 AM W/650 PSI. PLUG HELD. 16 BBLS OF CMT TO SURF. WOC. CUT OFF CONDUCTOR & 8 5/8" CSG. MAKE FINAL CUT & WELD ON 8 5/8" WH & TEST TO 500 PSI. NUBOP. NDBOP. CHANGE OUT SPOOL. NUBOP.
10-29-01: TIH W/DC. PU 3 DC TO TAG CMT @ 400'. DRLG FR 461-607'.
10-30-01: DRLG 607-684,872,944,1216,1529,1811,2125,2438,2567,2780,3271 3821,4000. TRY TO LOG WELL. BRIDGE @ 830'.
11-04-01: TIH W/BIT. WORK THRU BRIDGES FR 800-2200'. WSH TO BTM FR 3812-4000. HLE BRIDGED OVER @ 3812. HAVE NOT BEEN ABLE TO CIRC - TIGHT HOLE.
11-05-01: WRK STUCK PIPE - BIT @ 3782 TOP OF DC @ 3174. RAN FP. STJCK @ 3180. FREE @ 3150. BACK OFF @ 3133. TIGHT FR 3133-2980. TIH W/TOOLS & TAG BRIDGE @ 700. WASH THRU BRIDGES FR 700'-1000'.
11-06-01: WASH TO TOP OF FISH. SOME OPEN HOLE FR 1149-1400. REST OF IT WAS WASHED DN.

PLANS ARE TO PLUG & ABANDON THIS WELL. P&A INTENT IS ATTACHED FOR APPROVAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/8/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: _____