

**NEW MEXICO STATE LAND OFF.
SANTA FE, NEW MEXICO**

**DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE**

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. _____, N. Mex., _____ 19____
Santa Fe, New Mexico.

Dear Sir:

X

You are hereby notified that it is our intention to abandon _____ Well
R. L. Halley _____
No. _____ in _____ of Sec. _____ of Sec. _____, T. _____, R. _____
N. M. P. M., _____ Oil Field, _____ County.
We plan to commence work on _____, 19____.

The reasons for wishing to abandon the well are as follows:

1	NW 1/4	3	21	State "D"
Lea			Lea	33
104				

Plugged back solid from 4046' to 4010' with Rock, Steel Cuttings, and Lead Wool. Drove 18" Lead Plug with Steel Mandrel, Cemented with 6 Sx. Cement.

Filled Hole with Rock, Mud and Steel Cuttings and drove Lead Plug at 3780, Cemented with 6 Sx Cement.

Filled Hole with Mud and Rock to 1846', bridged to 1815' and drove Lead Plug at 1815', Cemented with 6 Sx Cement.

Filled Hole with Mud to cellar and cemented Cellar.

RESULTS:

The work **Effectively Plugged** abandoning the well is as follows:

Approved _____ 4/1/4 1930

Except as follows:

Sincerely yours *H. Reynolds*
Superintendent

Cranfill-Reynolds Co.,
Company or Operator.

By **7th Floor Esperson Bldg.,**
Position **Houston Texas**

Send communications regarding this well to

Name _____

Address _____

R. L. Halley
State Geologist or Oil and Gas Inspector.