

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B 6717
7. Unit Agreement Name
8. Farm or Lease Name Amerada State
9. Well No. 20
10. Field and Pool, or Wildcat Wilson Y-7R
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Wilson Oil Company
3. Address of Operator 206 Booker Bldg, Artesia, N.Mex. 88210
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>N</u> LINE AND <u>1980</u> FEET FROM THE <u>NE</u> LINE, SECTION <u>13</u> TOWNSHIP <u>21S</u> RANGE <u>34E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3661 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The lease has expired to State and well must be plugged.
Well completed 9-24-41 as oil well TD 3741'. TD 3736' Deepened 3829'.
Plugged back to 3600' with lead wool. Completed as small gas well in
open hole. 7" casing 3450' - 300 sx.
Propose to plug with 50 sx 3450' to 4600'.
Shoot 7" casing 1600' and squeeze 35 sx.
Shoot 7" casing 450' and squeeze 60 sx or circ. Set 15 sx. plug at
surface with regulation marker.

THE COMMISSIONER OF THE NEW MEXICO OIL CONSERVATION COMMISSION
HEREBY CERTIFIES THAT THE ABOVE IS A TRUE AND CORRECT COPY OF
THE INFORMATION CONTAINED IN THE ORIGINAL RECORDS OF THE COMMISSION
TO BE KEPT ON FILE.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. R. Lamb TITLE V. P. DATE 11-7-79

APPROVED BY Orig. Signed by Jerry Sexton TITLE Dist. 1, Supv. DATE NOV 9 1979